

Civil Engineering Studies

Transportation Engineering Series No. 142

Traffic Operations Lab Series No. 18

UILU-ENG-2006-2002



ISSN-0917-9191

**High Tension Cable Median Barrier:
A Scanning Tour Report**

By
Juan C. Medina
Rahim F. Benekohal

A report prepared by
Traffic Operations Laboratory
Department of Civil and Environmental Engineering
University of Illinois at Urbana-Champaign

Prepared for
Illinois Department of Transportation

January 2006

Technical Report Documentation Page

1. Report No. FHWA-IL/UI-TOL-18	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle High Tension Cable Median Barrier: A Scanning Tour Report		5. Report Date January 31, 2006	
		6. Performing Organization Code	
7. Author(s) Juan C. Medina and Rahim F. Benekohal		8. Performing Organization Report No.	
9. Performing Organization Name and Address Department of Civil and Environmental Engineering University of Illinois at Urbana-Champaign 205 N. Mathews Ave. Urbana, Illinois 61801		10. Work Unit (TRAIS)	
		11. Contract or Grant No.	
		13. Type of Report and Period Covered Scanning tour report 2005	
12. Sponsoring Agency Name and Address Federal Highway Administration (FHWA) – Accelerating Safety Activities Program (ASAP) and Illinois Department of Transportation (IDOT)		14. Sponsoring Agency Code	
15. Supplementary Proposal Title: a scanning tour to identify effective and efficient approaches of reducing the number and severity of freeway median crossover crashes.			
16. Abstract The Illinois Department of Transportation (DOT) coordinated a scanning tour to identify effective and efficient approaches of reducing the number and severity of freeway median crossover crashes. Representatives from Illinois, Iowa, Minnesota, and Wisconsin DOTs, and the University of Illinois, visited Ohio, Oklahoma, and Texas to learn from their experiences in the use of high-tension cable barriers, and to gather information on system characteristics and performance from the states and two manufacturers of high-tension cable barrier systems. Field- installed high-tension cable barrier systems from four manufacturers were observed: U.S. High Tension Cable System, Brifen WRSF, CASS, and Safence. These cable barrier systems seem to perform similarly when hit by passenger vehicles. The performance at redirecting or stopping vehicles was reported to be excellent, and no major drawback of using high-tension cable barrier systems was found. It was reported that crash severity was reduced significantly compared to other barrier systems and no fatalities had been recorded on crashes at locations with high- tension cable barriers. Some issues pertaining to optimum cable location, long-term benefit-cost analysis, TL-3 versus TL-4 requirements, 3-cable versus 4-cable systems, and others need additional exploration and experience to be addressed more precisely.			
17. Key Words High-tension cable, median crossover crashes, median barriers, U.S. High Tension Cable System, Brifen, CASS, Safence, NCHRP 350, scanning tour.		18. Distribution Statement	
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 25	22. Price

Acknowledgment and Disclaimer

The authors would like to thank the participants of the scanning tour for their suggestions, comments, and cooperation in preparing this report. In particular, we appreciate the invaluable assistance and cooperation of Mr. David Piper of the Illinois Department of transportation (IDOT).

This scanning tour report was prepared by the Traffic Operations Laboratory (TOL) at the University of Illinois at Urbana-Champaign. The Federal Highway Administration (FHWA), under its Accelerating Safety Activities Program (ASAP) and the Illinois Department of Transportation funded the Scanning Tour and preparation of this report. The contents of this report reflect the views of the authors, who are responsible for the facts and accuracy of the data presented herein. The contents do not reflect the official views or policies of IDOT or FHWA. This report does not constitute a standard, specification, or regulation.

Executive summary

The States of Illinois, Iowa, Minnesota, and Wisconsin are interested in installing and/or expanding the use of high-tension cable barriers for cross median protection on their highway systems.

These states took part in a scanning tour with the following objectives: 1) to learn from other states that already have experience in the use of high-tension cable barriers, and 2) to gather information on system characteristics and performance from the states visited and companies that manufacture high-tension cable barrier systems.

The Scanning Tour was founded by the Federal Highway Administration (FHWA) and took place from August 29, 2005 to September 2, 2005. The Tour included visits to Ohio, Oklahoma, and Texas DOTs and some of the cable systems manufacturing companies in those states.

Four proprietary high-tension cable barrier systems were observed: U.S. High Tension Cable System, Brifen WRSF, CASS, and Safence. These systems meet NCHRP 350 criteria for test level 3 (TL-3)¹, which is the main required standard in the visited states. The cable systems use ¾-inch diameter 3 x 7 strand cable ropes (may or may not be pre-stretched depending on the system) and weak posts to guide the cables through and maintain cable height.

The observed cable barrier systems seem to perform similarly when hit by passenger vehicles. The performance at redirecting or stopping vehicles was reported to be excellent, and no major drawback of using high-tension cable barrier systems was found.

It was reported that crash severity was reduced significantly compared to other barrier systems, no fatalities had been recorded on crashes at locations with high-tension cable barriers, and very few crashes had resulted in barrier penetration.

The selection of high-tension cable systems is based on a bidding process, but bidding specifications are not the same among the states though they all require a specific maximum dynamic deflection. Warrants for installation of median cable barrier generally depend on crash history, and are also dependent on roadway geometry and traffic volumes.

High-tension cable barriers may be installed on the shoulder or median, and are recommended for slopes no steeper than 6:1. The states visited preferred socketed posts over driven posts even though the former had a higher installation cost due to embedding the sockets in concrete foundations. The high initial cost seems to balance out over time mainly because post replacement is easier.

¹ The Brifen system has also been accepted at TL-4

The information gathered in this Scanning Tour provided valuable knowledge on the system characteristics, performance, and maintenance, although the states visited are still going through the learning process. Some issues including optimum cable location, long-term benefit-cost analysis, TL-3 versus TL-4 requirements, and 3-cable versus 4-cable systems, and others, need more exploration and experience to be determined precisely.

Table of Contents

EXECUTIVE SUMMARY	IV
INTRODUCTION	1
PARTICIPANTS	1
AGENDA	2
BRIEF INTRODUCTION TO HIGH TENSION CABLE BARRIER SYSTEMS	3
U.S. High Tension Cable System	3
Brifen Wire Rope Safety Fence (Brifen WRSF)	4
CASS	5
SAFENCE	6
STATE VISITS	7
Ohio	7
Selection and Application	7
Warrants and Criteria	8
Design and Construction	9
Current Installations	9
Brifen System	9
U.S. High Tension Cable System	10
CASS System	10
Maintenance	11
Emergency Vehicles	11
Visit to NUCOR Marion Steel Inc.	11
Oklahoma	13
Selection and Application	13
Warrants and Criteria	13
Design and Construction	13
Current Installations	14
Brifen System	14
SAFENCE	16
CASS System	16
Maintenance	16
Emergency Vehicles	17
Visit to Brifen USA Inc. in Oklahoma City, OK	17
Texas	18

Selection and Application	18
Warrants and Criteria	19
Design and Construction	19
Current Installations	21
Brifen	21
CASS System	22
Maintenance	22
Emergency Vehicles	23
GENERAL CONCLUSION	23
LIST OF APPENDICES	25

Introduction

Illinois, Iowa, Minnesota, and Wisconsin, are interested in installing and/or expanding the use of high-tension cable barriers for cross median protection on their highway systems. Both the Division and National FHWA representatives supported the idea of a scanning tour and helped to secure funding for it. Representatives from these four states participated in a scanning tour of sites in Ohio, Oklahoma, and Texas from August 29, 2005 to September 2, 2005. The purposes of the Scanning Tour were:

- To learn from other states who already have experience in the use of high-tension cable barriers, and
- To obtain information on system characteristics and performance from the visited states and companies that manufacture high-tension cable barrier systems.

A severe crash may occur when a vehicle crosses the median and hits an opposing vehicle. Median barriers are installed to prevent cross median crashes. Median barriers may not reduce the frequency of crashes due to lane departure, but they can prevent the cross median head-on crashes. Also, collisions with rigid barriers, such as concrete, may result in severe injury, either from the collision itself or from a secondary collision if the vehicle is reflected back into traffic.

Median barrier systems using high-tension cable are currently used in many states across the U.S. They are designed not only to reduce the number of cross median crashes, but also crash severity. Cable barriers can deflect more than other type of barriers such as W-beam barriers to reduce the severity of the impact. Cable barriers are also more adaptable to variations in the terrain profile and slopes compared to beamguard barriers, may withstand a second hit before repairs, usually require less grading and drainage work, and to some people they may be aesthetically more pleasing than other barrier systems. However, there are still questions about their performance, cost, installation, and maintenance that need to be answered.

Participants

The following participants came from the Illinois, Minnesota, Iowa, and Wisconsin Departments of Transportation and the University of Illinois:

Name, Position	Agency
David Piper, Safety Design Engineer	Illinois DOT
Deanna Maifield, Methods Engineer	Iowa DOT
Chris Poole, Office of Design	Iowa DOT
Gary Dirlam, District Traffic Engineer	Minnesota DOT
John Hanzalik, Metro Highway Maintenance Supervisor	Minnesota DOT
John Bridwell, Standards Development Engineer	Wisconsin DOT
Peter Amakobe, Standards Development Engineer	Wisconsin DOT
Juan Medina, Graduate Research Assistant	University of Illinois

The University of Illinois was responsible for preparing this report.

Agenda

The agenda included meetings and field visits with DOT representatives, and visits to cable systems manufacturing companies. The following is a summary of the main activities during the Scanning Tour:

Ohio (August 29th – 30th, 2005)

- *Meeting at Ohio DOT and field visit:*
Visited site: I-270 and Tuttle Crossing Blvd - U.S. High Tension Cable System²
Contact person: Dean Focke, PE Roadway Standards Engineer
Ohio DOT.
- *Visit to NUCOR Marion Steel Inc. plant:*
Contact person: Rich Mauer, National Sales Manager, Marion Steel Company

Oklahoma (August 30th – September 1st, 2005)

- *Meeting at Oklahoma DOT and field visit:*
Visited sites: - State Highway 75 – Hefner Parkway (Brifen)
- I-35 (Brifen)
Contact person: Faria Emamian, P.E. Engineer Manager,
Oklahoma DOT
- *Visit to Brifen USA:*
Contact person: Jerry Emerson, P.E. Marketing Engineer Brifen
USA

Texas (September 1st – 2nd, 2005)

- *Meeting at Texas DOT (Weatherford Area Office) and field visit:*
Visited site: I-20 (CASS – Brifen)
Contact person: Jimmey Bodiford, P.E. Area Engineer

The complete list of participants in each of the meetings can be found in Appendix 1.

² Rainy weather did not permit any close inspection of the installed U.S. High Tension Cable System

Brief Introduction to High Tension Cable Barrier Systems

Four different proprietary high tension cable barrier systems were observed in the Scanning Tour and will be discussed in this report: U.S. High Tension Cable System, Brifen WRSF, CASS, and Safence. The four systems meet NCHRP 350 criteria for test level 3 (TL-3). A modified version of Brifen WRSF also meets the requirements for test level 4 (TL-4). These cable systems use $\frac{3}{4}$ -inch diameter 3 x 7 strand cable ropes (pre-stretched or not pre-stretched depending on the system) and weak posts to guide the cables and maintain cable height.

The basic characteristics of the four systems are briefly described in this section. More information can be found in the manufacturers' product literature and in the NCHRP test conditions and results published by FHWA.

A summary of the systems characteristics and their performance in NCHRP 350 test type 3-11 is presented in Table 1. The table only includes information from official acceptance letters issued by the FHWA to the manufacturers that have been posted on the FHWA official website as of October 2005. This website is continuously updated and it can be visited to obtain the latest information on system designs and variations.

http://safety.fhwa.dot.gov/roadway_dept/roadHardware/longbarriers.htm

System	U.S. High Tension Cable System	Brifen WRSF	CASS	SAFENCE
Manufacturer	NUCOR Marion Steel Inc.	Brifen USA	Trinity Industries Inc.	Blue Systems AB
# of Cables	3	4	3	4
Cable Diameter	19mm diameter (3x7 strands/cable)			
Cable tensioning	Non-prestretched / Prestretched	Prestretched	Prestretched	Prestretched
TL-3 Post Shape	U-channel (Rib-Bak)	S-shape	C-channel	I-post or C-post
Cable Height Above the Ground	750mm, 650mm, 545mm	720mm, 675mm, 510mm (Height #1) or 720mm, 600mm, 460mm (Height #2)	750mm, 640mm, 530mm	720mm, 640mm, 560mm and 480mm
NCHRP 350 test 3-11 Approved	Yes	Yes	Yes	Yes
Post Spacing	2m or 3.8m or 5.1m	3.2m or 2.4m	2m or 3m or 5m	2.5m
Dynamic Deflection	1.6m (2m post spacing) 1.8m (3.8m post spacing) 2.31m (5.1m post spacing)	2.4m and 2.6m (3.2m post spacing, Height#1 and Height#2 respectively) 2.7m (2.4m post spacing Height#2)	2.06m (2m post spacing) 2.4m (3m post spacing) 2.8m (5m post spacing)	2.7m

Table 1. Systems characteristics and performance on NCHRP 350 Test 3-11

U.S. High Tension Cable System

The U.S. High Tension Cable System is a three-cable system. It is currently produced by NUCOR Marion Steel Inc., and uses Rib-BakTM cable line posts and 0.25-inch diameter

U-shaped hook bolts to guide the cables at the desired height. The manufacturer describes two procedures to install the posts: (1) directly embedded in the ground (driven), or (2) using cast-in-place or pre-cast concrete socket foundations. When using concrete foundations, it is important to get the socket flush with the concrete in order to avoid having the top portion of the socket exposed and to allow posts to shear off rather than bend. It is recommended that the foundation reinforcing bars be tied together to assure their proper placement and the resistance of the foundation.

The manufacturer recommends using non pre-stretched cable, but pre-stretched cable can be supplied upon request. A template to attach the hook bolts at the correct height is helpful in the installation process because the posts have one hole every inch.



Figure 1. U.S. High Tension Cable System

The system is typically tensioned at 5,600 lb, and anchored with a Texas Transportation Institute's (TTI) proprietary Cable Guardrail Terminal End. TTI's end treatment was designed for rocky or hard soils, and is NCHRP 350 approved (details on TTI's end treatments can be found in acceptance letter of U.S. High Tension Cable System – FHWA website). Upper and lower cables are recommended to be located on the side of the post closest to the roadway, leaving the middle cable on the opposite side.

For details on the most recent information about the NUCOR Marion Steel Inc. cable system, contact Rich Mauer, National Sales Manager, Marion Steel Company, or visit the following websites:

- Official website: <http://nsmarion.com/>
- Multi-state distributor of NUCOR system: <http://www.gsihighway.com/nucor>

Brifen Wire Rope Safety Fence (Brifen WRSF)

Brifen USA manufactures four-cable and three-cable systems, both are NCHRP 350 approved. The sites visited had only installed the four-cable system. The Brifen (**British**

Fence) WRFS uses an exclusive S-shape post in its TL-3 version. The manufacturer recommends only pre-stretched cables.



Figure 2. Brifen Wire Rope Safety Fence System

Posts are installed in concrete foundations with a minimum strength of 3,500 PSI or can be driven using a post with a soil plate. In the four-cable system, the three lower cables are interwoven around the posts and the upper cable is placed in a slot on the top of each post. The end treatment is a customary part of the design and extends 19 posts in total: 4 posts for the Wire Rope Gating Terminal (WRGT), and 15 posts for the transition to the line posts.

For detailed information on the Brifen system, contact Jerry Emerson, P.E. Marketing Engineer Brifen USA

Official website in USA: <http://www.brifenus.com/>

CASS

CASS (Cable Safety System) is a three-cable system by Trinity Industries, Inc. It uses pre-stretched cable, and the posts have an opening in the upper part to accept the cables, which are kept in correct position by wider slot sections at specified cable heights, a plastic cap on the top of the post, plastic spacer blocks, and a steel strap. Posts are installed in steel sockets that can be either driven directly into the soil, or cast in concrete cylinders. TTI's Cable Guardrail Terminal Ends are used to anchor the system.



Figure 3. CASS System

For more information on the CASS system contact Rich Figlewicz, Consultant-Highway Safety Products Division, Trinity Industries Inc.

Official website: <http://www.highwayguardrail.com/>

SAFENCE

Safence is a 4-cable WRSF system originally developed in Sweden by Blue Systems AB in 1993. Cables in the Safence system are factory pre-stretched. It uses I-section or C-section posts, which can be driven directly in the soil or installed in concrete cylinders. Spacers are placed between the cables to maintain adequate separation. Up to date, crashworthy end terminals have not been developed and tested.



Figure 4. Safence System

For more information on the Safence system, contact Michael Kempen, Vice President Safence.

Official website: <http://www.bluesystems.se/indexe.htm>

State Visits

The important factors in selecting the sites visited were:

- Variety and length of cable barrier systems installed,
- Experience in maintaining the systems (time after installation),
- Travel time to installation sites, and
- Travel time and accessibility to manufacturing companies.

Ohio, Oklahoma, and Texas, were chosen based on these criteria.

This selection allowed the Scanning Tour to learn about experiences with the three most commonly used cable barrier systems in the U.S.: Brifen Wire Rope Safety Fence (Brifen WRSF), U.S. High Tension Cable System, and CASS. A short section of a less commonly used system -Safence- was also observed in Oklahoma. The Scanning Tour also visited the production plants of the U.S. High Tension Cable System and Brifen USA.

In addition to the abovementioned systems, a fifth cable system called Gibraltar was recently approved by FHWA at TL-3 and TL-4 conditions. At the time the Scanning Tour took place, however, DOTs did not have enough experience using the Gibraltar system to schedule a field visit and gather information on installation, performance, and maintenance.

Ohio

Selection and Application

The use of high tension cable in Ohio was motivated by a series of 11 median crossover accidents that caused 14 fatalities in a 12-mile segment of I-75 starting in October 2001. Crashes were considered unrelated to highway geometry because no common crash cause could be identified.

Ohio DOT considered using standard W-beam barriers, concrete barriers, and high-tension cable barriers to prevent more median crossover crashes. Ohio DOT had removed the generic (low-tensioned) cable system from its standards in 1965 because of safety and maintenance concerns. The generic cable system does not protect against second hits until it has been repaired. Also, Ohio DOT did not have personnel with knowledge on the generic cable system.

Given these options, and based on a combination of estimated costs and expected performance, Ohio DOT decided that the most appropriate barrier for median crossover protection along I-75 was the high-tension cable.

Ohio DOT decided to install the Brifen WRSF system, because at the time it had been proven for more than 15 years in European countries and Australia, and it works under specified maximum deflections. The system is also NCHRP Report 350 accepted, and reduces the concerns of second hits. Ohio DOT was able to draw on the experiences of North Carolina and South Carolina. Also, Oklahoma DOT provided information on the Brifen system, since they installed the first segment in the United States.

Estimations made by Ohio DOT indicate that cable median barrier systems are more cost effective and less damaging to vehicles than many other median barrier systems. Cable systems are said to be much cheaper than concrete barriers and prevent vehicles from bouncing back into the road lanes.

Moreover, geometric characteristics on Ohio's freeways are favorable to cable barrier systems, where most freeway medians are 60 feet or more in width, with slopes of 6:1 or flatter, and with a traversable ditch, usually located in the center of the median.

The reduction in the number and severity of the crashes is Ohio DOT's primary safety objective. The "ODOT Business Plan 2004 & 2005" specifies these goals, among others:

- To reduce the frequency of crashes by 10 percent,
- To reduce rear-end crashes by 25 percent,
- To reduce the crash fatalities to not exceed one fatality per 100 MVMT.

Median barriers in Ohio have helped address these goals by reducing the annual number of deaths caused by median crossover crashes by 17 (16 percent of the total number of crash fatalities).

Warrants and Criteria

Warrants, based on a benefit-cost analysis, are used to select candidate locations for cable barriers, rather than deciding on a case-by-case basis. High priority is given to installations on multilane roadways with median widths less than 76 feet, and traffic volumes exceeding 36,000 AADT. Multi-lane roadways with median widths between 76 feet and 84 feet, traffic volumes greater than 26,000 AADT, and with a poor crash history are also considered for high-tension cable installation.

High-tension cable barriers are also considered for add-lane projects on freeways, if the new traffic lanes are added on the median side. The resulting reduced median width may meet barrier warrants.

Ohio DOT has also decided to retrofit safety "hot spots" with cable barriers to reduce the severity of crashes. On the other hand, cable barriers are not considered for roadside

protection, because the numerous driveways in non-fully controlled roadways would require more end terminals, and ultimately more expensive systems.

Design and Construction

Ohio DOT designs high-tension cable barriers specifically for each site. No standard detail drawings have been developed yet. Cable barrier is bid based on maximum dynamic deflection and NCHRP 350 test level (TL-3 is currently used as the standard because most hits don't involve trucks). No differences between 3-cable and 4-cable systems are specified in the bidding process.

Ohio DOT originally believed that the ideal location for cable median barrier was the bottom of the median ditch. However, some concerns arose because the drainage structures are often installed at the same location, and mud and wet conditions can make repairs very difficult for maintenance crews. To avoid these problems, the cable barrier is placed at least 8 feet from the bottom of the median ditch, although Ohio DOT doesn't recommend the use of mid-slope barrier at locations where the median slope is steeper than 6:1. Mid-median or a single run of a shoulder mounted barrier are the current preferred placement locations. Shoulder mounted cable barriers may require dual runs, one on each side of the median, as the cable system has not been tested for hits coming up ditch on the backside.

Current Installations

To date, three different high-tension cable systems have been installed in Ohio: Brifen WRSF, U.S. High Tension Cable System, and CASS. In general, it is highly recommended to use socketed posts instead of driven posts for all systems, despite some difficulties pulling posts out of the sockets in wet conditions.

Brifen System

A Brifen WRSF cable barrier was installed in the median along 14 miles on I-75 by the year 2003. I-75 is a six-lane freeway with 4-foot paved median shoulders and a 60-foot wide ditched median with 6:1 slopes. The barrier was installed on the side of the median slope at 10 feet off the center of the ditch, with a post spacing of 10 feet 6 inch, and a design deflection of 7.9 feet. The barrier flips sides depending on the existing structures along the road. Existing barriers were kept separate from cable system.

Climate conditions in Ohio are suitable for the standard Brifen installation, where the frost line and the depth of concrete posts are both 36 inches.

Most of the Brifen posts were originally driven on the median slopes, but based on the maintenance experience after several hits, it was decided to install concrete foundations on those damaged locations and use socketed posts to facilitate repairs.

Since the Brifen system was installed, about 200 hits have been reported, with no fatalities and one penetration.

In January 14, 2004, a passenger car destroyed 14 Brifen posts and penetrated the barrier. The cause of the penetration was not clear from the site evidence. Cables sagged to approximately one-half of the correct height. District 8 did repairs two months after the accident. According to information provided by Richard Butler from Brifen USA, the concrete foundations were retrofitted, and yielded due to their lack of depth and low resistance. This condition caused the concrete footers to move in the soil, thus not allowing the posts to bend, and creating a ramp for the vehicle to “ride up” and over the system.

U.S. High Tension Cable System

U.S. High Tension Cable System was installed in the median along 12 miles of I-270 by October 2004. The posts were placed at the edge of the paved shoulder and socketed in concrete foundations. Post spacing is 6.5 feet for a design deflection of 6.5 feet. More than 30 hits have been registered since installation with no fatalities or penetrations.

U.S. High Tension Cable System posts shear as a consequence of a hit, allowing cables to maintain their height. However, posts at some locations have bent, allowing the concrete foundation to be pulled out of the soil. Other posts have also sheared off at the bottom of the sleeve, particularly during the spring thaw. Installing the locking bolts in the U.S. High Tension Cable System can increase repair time, but they hold the cable at its proper height more securely than the other systems. Otherwise, the high-tension cable can cause the posts to “float” where the barrier crosses local depressions.

Many of the TTI anchor foundations were redesigned and retrofitted by the cable manufacturer because some concrete foundations became loose and moved. A check using Marion Steel’s meter revealed that in one occasion the cable was not properly tensioned, but no conclusive causes were found. Tension checks need to be conducted on a regular basis to ensure proper service conditions. It was observed that Ohio DOT overlapped ends of cable barrier behind the guardrail at some locations.

Rainy weather did not permit any close inspection of the installed U.S. High Tension Cable System.

CASS System

Three miles of the CASS system were completed in October 2004. The barrier was placed at the edge of the paved shoulder on an asphalt mow strip. Posts were installed in sockets with concrete foundations and spaced 10 feet with a design deflection of 7.9 feet. Anchor movement has not been a problem, even though the anchor system is also based on the same TTI design used for the U.S. High Tension Cable System. At some locations, CASS posts have bent inside the socket. Based on information provided by CASS manufacturer, posts will bend 99.9 percent of the time at or near ground level, and they are not intended to shear.

About 25 hits have been recorded in the 3-mile stretch with the CASS system with no fatalities or penetrations.

Maintenance

At locations with cable barrier, about 12 percent of the crashes resulted in injuries (mostly minor injuries), and no fatalities have been recorded. The total number of crashes has increased by about 30 percent since the cable installations, and according to Ohio DOT, this increase was attributable to the cable presence.

A document titled “Ohio DOT Field Visits to Cable Median Barrier Projects” contains detailed information on the observations and results of several field visits during February and March 2005 (See Appendix 2). The report concluded that all high-tension cable barrier systems being used are performing satisfactorily and there is no clear preference for one particular system.

State Maintenance forces repair the Brifen cable installation in Ohio. Typically, repairs are done 1 or 2 weeks after a crash in good weather, and up to 2 months after a crash in bad weather conditions. Most crashes require 4 - 5 posts to be replaced, but as many as 43 posts have been damaged in one crash on the Marion system³. A worker was injured during one repair of the Brifen system because an improper weaving technique was used.

Mowing and snow plowing is a concern that is recommended to be addressed at the design stage. With regards to Ohio DOT, snow plowing has always been done for the full shoulder width, thus top mounted barriers are subject to snow damage.

Emergency Vehicles

In relation to response times of emergency vehicles, roadway conditions in areas where high-tension cable barriers have been installed are favorable, since interchanges are typically closely spaced. However, in some cases emergency crossovers are located every 1½ miles and the cable runs are terminated at those crossovers.

Visit to NUCOR Marion Steel Inc.

NUCOR Marion Steel Inc. is the current producer of the U.S. High Tension Cable System. On June 3, 2005, NUCOR bought Marion Steel Inc. and about two months later it also bought SAFERoads, which previously manufactured and sold the system. NUCOR Marion Steel Inc. is committed to continue the production and development of the U.S. High Tension Cable System.

The visit to the NUCOR Marion Steel plant, in Marion, OH, was divided into three main parts:

- A meeting with the company representatives,
- A tour through the plant, and
- An inspection of a short piece of the U.S. High Tension Cable System installed in the company parking lot.

³ In a related comment, it was mentioned that Minnesota State Patrol tags damaged items with the accident report number to facilitate the insurance claims. Funds are returned to the district budget

Details on installation procedures and characteristics of The U.S. High Tension Cable System are included in the product Installation Manual. However, since some of the comments and recommendations given by the company representatives on the use and installation of the U.S. High Tension Cable System are not contained in the Installation Manual, they are included here:

- Development efforts on the U.S. High Tension Cable System are focused on the improvement of the post resistance and stiffness. More resistant and brittle posts will break off rather than bend.
- NUCOR Marion Steel Inc. hopes to reduce the dynamic deflection to 3 feet within the next 3 years. However, it was pointed out that less deflection results in more vehicle damage because less energy is being absorbed by the cable system.
- Limiting the distance between end treatments to ½ mile is preferable. This recommendation helps to control deflections, and also reduces the amount of system that can be taken out by a hit on a terminal.
- For concrete foundations, it is advisable to punch the holes in the soil instead of drilling them, because it compacts the soil in the hole and leaves less spoil.
- Latest version of the post sleeve is cheaper but more flexible because of its cylindrical shape. The previous version was square.
- NUCOR Marion Steel Inc. is supportive of the use of driven posts. Their posts are often driven in other applications such as signage support.
- Using reinforcing bars in the concrete foundations is highly recommended by NUCOR Marion Steel Inc. to increase longevity.
- Representatives from NUCOR Marion Steel Inc. recommended non pre-stretched cable over pre-stretched cable. It was stated that after a number of crashes, the standard cable would be stretched as much as the pre-stretched cable. The manufacturer said that eventually both will be equivalent and the initial cost of the pre-stretching process does not result in system benefits.
- NUCOR Marion Steel Inc. is coming out with a new digital tension meter manufactured by DILLON Inc.

The main processes in the NUCOR Marion Steel plant to manufacture steel, and obtain different forms of steel elements for the cable barrier systems are shown in Appendix 3.

Oklahoma

Selection and Application

The first installation of high-tension cable barrier for median crossover crashes in the United States was completed in Oklahoma in 2000. A median crossover barrier was required along the Lake Hefner Parkway in State Highway 74, Northwest Oklahoma City, in response to a series of crossover crashes that left 4 fatalities between June 1997 and May 2000. At this location, State Highway 74 is a six-lane freeway with a grass median between 36 feet and 42 feet wide, and with volumes of 108,000 AADT as of 2000, and increasing.

Local residents were concerned about blocking the scenic view of the lake, for which concrete or guardrail barriers were not deemed a viable option. High-tension cable systems were considered appropriate because they not only can reduce crash severity, but also complied with the aesthetic requirements.

Oklahoma DOT selected Brifen WRSF, and FHWA approved the experimental use of the high-tension cable in a 1,000-foot section. A private contractor carried out the installation. At the time, the end terminals were not NCHRP 350 approved, thus existing structures or additional barriers shielded the end terminals.

Deflections are an issue for the generic cable because it limits the locations where this system could be used. Oklahoma DOT stated that while the generic cable typically deflects between 11 feet and 12 feet, deflection for the Brifen high-tension cable system is about 6 feet to 8 feet. Also, in contrast to the generic cable system, high-tension cable is designed to remain serviceable after a first hit.

Warrants and Criteria

Priority for median barrier installation is set based on location, frequency, and severity of crashes. For location selection, the Traffic Engineering Division prepares a series of maps showing the locations of crossover collisions (a crossover collision was defined as “run-off road left” followed by a collision on the other side). These locations were then ranked by severity index, and selected in priority order.

Design and Construction

Cable system selection follows a bidding process with specified post spacing. There is not a consensus on whether the number of cables used by the system should be part of the specifications or not. Satisfactory experiences in Ohio with 4-cable systems, and the elevated number of truck crashes, have suggested that continuation with this type of cable barriers can be positive. However, not enough experience on 3-cable systems has been acquired yet.

Current Oklahoma DOT standards require the systems to be NCHRP 350 TL-3 approved. There is some interest in moving to TL-4 requirements, but future change to TL-4 need to be further studied because the cable height would be raised and performance with small cars is a concern.

Location of the barrier has been a major concern and is currently determined in a case-by-case basis. Oklahoma DOT has observed a tradeoff between barriers at or near the median center, which can reduce the potential for nuisance hits, and barriers on the edge of shoulders, which can reduce the amount of sand and fine particles getting into the foundation sleeves, easing post replacement. At some locations where the cable barrier has been placed near the median center, median drains were adjusted to allow the cables to maintain a level profile while maintaining hydraulic capacity. In some cases, steep median slopes have been reduced to a maximum of 6:1 for cable installation.

Barrier posts are installed in socketed concrete foundations. Driving posts can reduce initial costs, but it is believed that maintenance costs could be higher in the long run. Oklahoma DOT prefers “punched-in” holes to drilled holes. As mentioned previously, this method compresses the soil around the hole and improves resistance.

The use of high strength concrete, instead of reinforcing bars for post foundations in the Brifen system, has shown good results. No broken foundations have been reported up to date. CASS installation used reinforcing bars in footings, but no data is available for evaluation yet.

Existing safety devices, such as sand barrels or guardrail barriers, remained in place after cable installation and were shielded by the cable. Mow strips have been placed under the cable barrier in two installations, but Oklahoma DOT doesn’t believe it is essential for the cable systems in all projects. It is recommended to place reflective tape on the plastic cap of the posts to reduce hits at night and help emergency vehicles to identify crossover points.

Current Installations

Currently, there are three different high-tension cable systems installed in the Oklahoma City Metropolitan area: Brifen WRSF, Safence, and CASS System (See Appendix 4). Oklahoma DOT designed the installations for Brifen and Safence systems, but the manufacturer – Trinity Industries Inc, designed the CASS installation. In terms of performance, Oklahoma DOT indicated satisfactory results for all three systems. Crash reports summarized below included data as of July 31, 2005, and can be found in detail in Appendix 5.

Brifen System

The first Brifen test installation was extended from 1,000 feet to 7 miles in 2001. Cable was installed in two sections of 2 miles and 5 miles long between end treatments. No negative experiences have been reported due to the long cable runs. The barrier was not located at the center of the median, as the first 1,000-foot stretch was, but on a paved mowing strip just outside the southbound shoulder. This placement was also preferred over the center median because the drainage inlets created a slope too steep for an adequate installation (see photographic material in Appendix 6).

Oklahoma DOT provided to the Scanning Tour participants two reports about the Brifen installations:

- “Brifen Wire Rope Safety Fence Final Report” by Faria Emamian P.E. Engineer Manager in Oklahoma DOT, dated March 2003 – this report includes a detailed collision analysis, and maintenance and repair issues on the 7-mile stretch on the Lake Hefner Parkway (See Appendix 7).
- “Oklahoma DOT Experience with Brifen Wire Rope Safety Fence on Lake Hefner Parkway in Oklahoma City”, by Randy B. Lee, P.E. Division IV Traffic Engineer in Oklahoma DOT, dated June 24, 2004 – Mr. Lee was involved in the maintenance of the Brifen installation. The report includes some comments on the system (See Appendix 8).

Some of the most relevant comments from these two documents, as well as additional information provided by Oklahoma DOT related to the Brifen installation are described below:

- As of May 10, 2004, a total of 238 hits have been reported in the system, requiring replacement of 1279 posts, for an average of 5.3 posts per hit.
- As of June 24, 2004, the average cost charged by the maintenance contractor for the replacement of each post was \$51.00.
- No fatalities and 3 injuries have been reported. This represents a significant reduction in crash severity compared to a similar time frame before the barrier installation.
- It was estimated that police accident reports have only been filed on approximately 30 percent of the hits, indicating very light vehicle damage.
- One person using only hand tools usually makes a 5-post repair in 15 minutes. It is not recommended, however, to lift the cables by hand for safety of workers.
- The system has remained serviceable after multiple hits at the same location.
- The use of long distances between anchors has not generated any loss of cable tension, nor turnbuckle damage after the hits.
- The largest vehicle to impact the barrier was a full size school bus, which was redirected safely after the driver had a heart attack.
- In a few cases, cables dropped down to the ground when many posts were knocked out. (Repairs were made within 2 hours, as required by the contract for these types of hits). It should be noted that typical hits don’t have this effect on the cable barrier.

- The mow strip placed under the cable system (4 feet wide and 4 inches thick) is not effective since hand mowing is still needed. A soil herbicide is mentioned as a possible solution.
- Low front vehicles, such as sports cars, can potentially penetrate the barrier because their suspension is compressed at the bottom of the ditch and the bumper can underide the lower cable.

A second installation using the Brifen system was completed in September 30th, 2004, along 6.3 miles on I-35 in the Norman area, Cleveland County. Twenty one hits have been reported since installation, with one property damage crash and no fatalities or injuries. During the last 5 years prior to the barrier installation, 6 fatal, 16 injury, and 9 property damage crashes were reported in this stretch of road.

SAFENCE

A one-mile test of the Safence system was installed as a demo, promoted by the manufacturer, along I-35 north of Purcell, McClain County (see Appendix 6). The barrier was completed on the same date Brifen's second installation was completed, September 30, 2004. Because of its short length, only 3 crashes have been reported since cable installation, all of them without injuries or significant vehicle damage. During the last five years prior to the barrier installation, 1 fatality, 5 injuries, and 1 property damage crash were reported in this stretch of road. Similar concerns to those found in Texas when lifting CASS cables by hand for maintenance activities may be expected with the Safence system (See CASS System Section in Texas Visit below).

CASS System

The CASS system was recently installed (August 26, 2005) on I-35, McClain County. Up to date, no crash data is available to provide performance results on this system. A total of 3 fatal, 1 injury, and 3 property damage crashes were reported the last five years prior to the barrier installation.

Maintenance

The maintenance on the Brifen systems is contracted out. Oklahoma DOT does the maintenance on the other systems. Repair parts have been readily available and are delivered in a timely manner. The average repair takes about 20 minutes. So far, the repairs have only involved replacing posts and some of the hardware associated with posts.

Maintenance staff generally prefers the cable barrier to be located in the middle of the median. There have been no significant wintertime maintenance problems.

See Appendix 9 for Oklahoma's Questionnaire responses.

Emergency Vehicles

To minimize the effect of the limited number of crossovers for emergency responders, Oklahoma DOT has considered the option of flipping side of the roadside barrier and overlapping the end treatments at the flip points to provide turnarounds. This would be done at overhead bridges or other sites where topography provides convenient turnaround locations.

Visit to Brifen USA Inc. in Oklahoma City, OK

Brifen representatives met with the Scanning Tour at the Brifen USA plant, located in Oklahoma City. Some of the comments discussed in the meeting prior to the plant visit, as well as recommendations and comments at the plant are included below:

- Brifen recommends the use of pre-stretched cable for the barriers. The pre-stretching process takes slack out of the cable and equalizes loads in the 21 wires of the rope.
- There is a mini-anchor effect generated by the cable weaving. Friction between cable and post dissipates some energy from hits. Testing has shown that tension from a test-level impact does not transfer beyond 70 posts from the impact location. This helps to keep the effect of a hit under a limited section in a long stretch of the Brifen system.
- Crash tests were performed on 600-meter sections (about 2,000 feet), which is considerably longer than the 100-meter sections used in standard NCHRP 350 TL-3 test.
- Although early systems were installed with 14-inch by 36-inch foundations, the standard is now 12 inches by 30 inches as tested with the TL-4 system. TL-4 version was reinforced with a u-shaped rebar ring welded to the bottom of the steel socket. Driven posts are available, but not recommended due to higher maintenance costs.
- It was not recommended to use pre-cast concrete footings because it is not easy to perfectly match the footing volume with the volume of the hole in the ground. As a consequence, footing can become loose and move after an impact.
- Turnbuckles can be placed at posts. Special posts with extra wide slots are provided in such cases. However, no more than 2 turnbuckles should be placed within 10.5 feet to avoid a single crash hitting more than one connection.
- Brifen uses solid body turnbuckles, which are claimed to be sturdier than open body turnbuckles.
- Standard line posts can be used down to a 200-meter radius (about 656 feet).

- Construction inspection is very important.
- For median locations it is recommended to install the Brifen WRSF at least 10 feet from the bottom of the ditch on a slope no steeper than 6:1.
- A black plastic “excluder” (resembles a black Frisbee) is placed at the base of the post and covers the sleeve. It is meant to keep out larger objects. Finer elements may get into socket, but there is no need to clean them other than when the posts are being replaced after a hit.
- There have been 300 hits on the Hefner Parkway system, which is at the shoulder. The proportion of hits has been roughly 2:1 nearside vs. far side.
- Minnesota DOT asked if a TL-5 test would be conducted. Brifen doesn’t think the investment is justified. Also, there are some substantiated reports of the TL-3 system containing and redirecting trucks well beyond the TL-3 weight.
- It is possible to terminate a Brifen barrier by connecting it to a guard rail.
- Current cost per post is \$18.30. Other parts cost less than \$5 per post (as of August 2005).
- During the field trips, it was observed that the top of the concrete foundations are constructed with a convex top (or dome). The height of this dome needs to be limited because it affects the ground clearance of the bottom rope, which is critical.

Texas

The Scanning Tour visited the Weatherford Area Office in Texas⁴. This office is part of the Fort Worth District of the Texas DOT. It is located west of Fort Worth and is responsible for two counties – Parker and Palo Pinto. There are 52 maintenance, and 19 Design/Construction employees on staff.

Selection and Application

In Texas, the Safety Bond Program, approved by voters in 2003, is providing safety improvement projects totaling over \$600 millions. Reduction in the crash frequency and severity is one of the primary goals of the Safety Bond Program. It was mentioned that almost all fatalities (about 96 percent) in the interstate system had been cross median related.

⁴ Due to time constraints, a visit to the Trinity Industries Inc. facilities in Dallas, TX, was not possible for this Scanning Tour. However, representatives from Trinity Industries Inc. have been supportive to this Scanning Tour and provided the participants with information on their CASS system.

Warrants and Criteria

Median barrier projects are supported by warrants. The Weatherford Area Office, in coordination with the Traffic Section at the Forth Worth District Office, analyzes traffic reports and crash data to prepare a list of the candidate locations for improvements. Currently, cable median barriers are warranted on freeways only, in particular, freeways with medians narrower than 44 feet (measured between edge stripes).

Cable barriers are thought to be cost-effective. The improvement in safety translates in lower crash severity and reduction in total expenses, but a precise evaluation will require more time and data to account for maintenance costs in the long run. Under a high hit rate, it is expected that cable barriers are more expensive compared to concrete barriers. However, low severity of crashes with cable barriers seems to be also a decisive factor in its favor.

Design and Construction

Selection of cable system is based on a bidding process. Requirements for bidding companies are based on price, NCHRP 350 TL-3 approval, and maximum deflection (typically 8 feet). No distinction is made between 3-cable and 4-cable systems in the bidding process. TXDOT has not planned to change NCHRP 350 requirements from TL-3 to TL-4 because cable performance under TL-3 has been satisfactory for all types of vehicles.

TXDOT specifications for cable barrier systems are included in the Special Specification 5084, Miscellaneous Constructions Section, in the document “Texas DOT specification 2004”. A copy of the specification sheet was provided to the Scanning Tour (See Appendix 10).

Cable barriers are preferred near, but offset from the edge of the shoulders. Brifen and CASS systems were installed at about 14 feet from the edge of the inside travel lane, where typical median shoulder is 6 feet wide. This placement provides a more consistent profile than installations in the center of the median, because it prevents difficulties caused by drainage structures and uneven ground, and reduces chances of weaker soils at foundation depth. Sharp changes in the profile cause significant variations in the height of the cable above the ground, since the system is under high tension and cable tends to follow a straight line rather than the actual profile line over short distances.

The longest run of cable between anchors is about 4 miles. The stretches of cable are installed from bridge to bridge with no crossovers, except for one location, and barrier is usually lapped behind the approach guardrail or is shadowed by the downstream end of the bridge.

On future works, a more convenient layout for emergency vehicles has been planned. Cable will change median sides at each overhead structure, and end points will overlap to allow crossovers.

A 4-foot wide by 3-inch thick asphalt mow strip was constructed to help reduce cable barrier maintenance. It is believed that the strip also makes cable barrier more noticeable for first responders, who may suddenly need to cross the median in the case of an emergency situation. Reflective tape on top of the posts is also recommended to increase barrier salience and avoid such situations.

It was recommended to control the water level at mow strip to avoid premature asphalt deterioration and additional maintenance. Even though cable barrier doesn't need to be mowed because of the asphalt strip, TXDOT protects the installation from damages caused by mowing contractors by charging them \$100 per post damaged.

Drilling post foundations was the leading activity during installation. About 50 12-inch-diameter holes were drilled per day/drill truck. Posts were installed in reinforced sockets with concrete foundations, including locations with hard rocky soils. A defective 36-inch foundation on sandy soil was reported pushed out of the ground in I-635, near Dallas.

To adequately secure the turnbuckle connections, Brifen recommends fully engaging the threads into the turnbuckle before making final connections. Because cable is pre-stretched, it doesn't need much length to be pulled out to achieve the required tension, and not much more thread engagement will be gained while tensioning.

During these initial installations, it has proven important to be familiar with system details during the installation process, in order to timely address contractor's questions. Representatives from Brifen and CASS were also present during installation to give technical support as needed. At one location, a Brifen anchor foundation was built with flat top instead of a 12-degree inclination. Brifen took engineering responsibility and corrected the structure using a special wedge. In some situations, installation misunderstandings or errors were avoided by active on-site guidance to the contractor from manufacturer's representatives. Some examples of these misunderstanding or errors were related to the purpose of the inspection hole in the field splice, the number of required bolts for the anchor, and the requirement for threads showing beyond the shoulder of the nuts.

The contractor is responsible for any damage to the barrier prior to final acceptance. This contractual requirement protects DOT from additional costs during installation, but it may delay completion of functional smaller sections of barrier, and encourage contractor to finish all post installations first, and only put the cable up just before project acceptance. This was noticed to be an issue in the Weatherford Area Office projects.

In order to incrementally open barrier to service, future modifications in long projects may include accepting small road sections as soon as the cable installation is completed. The contractor put up all the posts before installing the cable on the first 21 miles installed in their area. On future projects they will accept completed segments.

Current Installations

21 miles of cable barrier were installed in Parker County: Brifen (10.5 miles) and CASS (10.5 miles), both on I-20 and I-30 (see photographic material in Appendix 11 and Texas DOT design examples in Appendix 12). Post spacing was 10 feet 6 inch in the Brifen system and 10 feet in the CASS system. The complete project cost was \$1.4 million for the 21-mile roadway stretch, where typical volumes are close to 68,000 AADT.

It was decided to install cable barrier along I-20 in Parker County for the following reasons:

- History of crashes, including crossover and head-in crashes (An average of 2 to 4 crashes were reported each week).
- The junction between I-20, I-30, and I-820, is very complex and generates a concentration of crashes in the surrounding areas.

Despite few very specific cases with minor issues, performance of both Brifen and CASS systems is similar and very satisfactory. No vehicles have penetrated the barrier.

Press reaction to cable performance has been balanced. Initially, poor press pointed out concerns due to lost time for emergency response. However, good comments have been written after significant crashes that did not go through the median. It seems that cable barriers have good acceptance among the public in general. The community has demanded cable installation at some locations with severe crash history.

Brifen

As many as 30 posts or more have been taken out in the Brifen system after a hit, but about 15-20 posts are damaged by an average hit in both systems. Performance of the high-tension cable systems is kept up to date by filling out a repair log and an accident report form for each hit (See Appendix 13). Funds recovered after damage claims are deposited into the General Fund unless damage is higher than \$25,000.

Some crashes have reportedly left the Brifen cable laid down after some impacts. TXDOT has observed sag in both systems after a few significant hits, but sag has been more common in Brifen. No detailed information was given on the actual cause of the sag in Brifen system, but the cable straightening when taking posts out (loosening the weaving), and the fact that bigger vehicles have hit Brifen and damaged more posts, may both be contributing factors to this issue.

On one occasion the Brifen system was hit by a large truck. The system stopped the vehicle, but a cable came loose from the turnbuckle. The male end of the threaded connection was left intact after the separation, and it seemed that the connection failed because it was shallowly threaded. A special splice piece was fabricated to repair the separated cable.

At a few locations, Brifen posts have bent and become stuck inside sockets on impact, making it difficult to pull them out and complete the maintenance. The plastic spacer pegs used in the Brifen system have broken off easily. An increase of the pressure on the

pegs caused by the weight of the cable or changes in elevation may be enough to overcome the peg resistance. Dust covers in the Brifen system are reportedly difficult to get off the posts, and sometimes it is more troublesome to reuse them than place new covers instead. Richard Butler from Brifen USA commented that the problem with the posts was related to component manufacturing tolerances and that it was corrected. The chemistry of the dust covers was modified to eliminate difficulties removing them from the posts.

The Brifen spreader bar is useful for replacing posts when 2 workers are doing the repairs, but the bar is not required if a 4-person crew is on the job. Special attention needs to be given to the cable weaving when replacing many posts in the Brifen system. A recommendation to ease the weaving process is to replace posts every other position, and then weave the cable as the intermediate posts are placed. Failing to follow an adequate weaving technique may cause significant delays to repairs.

CASS System

The CASS system has also been hit by large vehicles. In August 2005, two 18-wheelers and a GMC Jimmy SUV were involved in an incident on I-20. The cable system prevented an 18-wheeler from crossing the median. The cost repair was estimated at about \$2,000, and no injuries were reported.

Posts in CASS system beyond the actual impact zone can be opened up at the top during the collision. Sometimes the posts can be straightened back, but need to be replaced otherwise. Trinity Industries Inc. does not recommend trying to straighten bent posts. Plastic spacers between cables in the CASS system are compressed and sometimes bent. In the Texas installation, CASS cables are too tight to be lifted by hand. When repairing the system, it is not recommended to lift cables over the post by hand because this places hands and backs in potentially vulnerable situations.

Maintenance

Maintenance is carried out by State forces, which were initially trained by manufacturers. Current TXDOT maintenance employees are now training new workers, assuring knowledge transfer over time.

Repairs are generally done the next working day, during daytime. Partial repairs are recommended in bad weather conditions to at least insure cable height is correct until the full repair is done. Wintertime issues are not a significant concern for cable barriers in Texas because there is usually not significant snow accumulation or frost heave effect.

Additional mechanical assistance, such as boom trucks or tripods, will facilitate the repairs significantly, in particular to pull stuck Brifen posts, and to lift and place cables in the slot of CASS posts.

Cable tension is not commonly re-checked after repairs, but some readings have been taken in the field. Differences in the readings from CASS (Digital) or Brifen (Analog) meters have been found to be about 500 lb, but it is not known which meter is more

accurate. As a preventive measure, TXDOT recommends requiring the meter manufacturer to calibrate the device before delivery, preferably in the United States.

A stock of repair parts is continuously kept indoors in the Weatherford Area Office (posts are stored outside). A customized trailer with individual compartments is currently used to carry all parts, including posts, with a capacity of about 40 posts. Parts for both Brifen and CASS are purchased directly from the manufacturers, which offer lower prices than third-party suppliers.

From the maintenance point of view, cable systems are effective but intensive to maintain. However, workers believe reduction in fatalities is worth the additional maintenance work compared to other types of barriers. It was also noted that maintenance crews would rather respond to repair the cable system than to provide traffic control for a fatal crash response.

Emergency Vehicles

TXDOT recommends informing first responders about the need to keep cable barrier systems and to avoid cutting cables, as well as offering educational sessions to tow truck drivers and other interested groups. It is also advisable not to loosen the turnbuckle once the cable is in place because pulling it back to its previous tension is very difficult. TXDOT conducts meetings with Fire Departments and tow companies on a regular basis to reinforce the message and since the two companies have considerable turn over in personnel.

General Conclusion

Based on the experiences shared by DOTs in Ohio, Oklahoma, and Texas, as well as the product information provided by manufacturers of the U.S. High Tension Cable, CASS, and Brifen systems, the following general conclusions can be drawn on the high-tension cable barrier for median crossovers:

- In recent years, there seems to be an increasing trend in median crossover crashes in all 3 states visited and all 4 states that sent representatives to the tour.
- The median cross over protection systems can reduce the fatalities and life changing injuries due to median crossover crashes.
- High-tension cable systems have been successfully used for median crossover protection on highways with wide medians and flat median slopes. There is potential for use in other conditions, but more experience and performance testing in the U.S. are needed.
- The general performance of the cable barrier systems, at redirecting or stopping vehicles, seems to be excellent.
- All cable barrier systems observed in the Scanning Tour (Brifen, U.S. High Tension Cable System, CASS, and Safence) seem to be perform similarly when hit by passenger vehicles. Further experience and testing is needed to quantify system capacity for heavy vehicles.
- No major drawback of high-tension cable barrier systems was found. Installation and maintenance issues can be improved with experience.

- While maintenance of the barrier system requires workers to be exposed to highway traffic, traffic control and cleaning up after vehicle crashes also requires workers to be exposed to highway traffic. Repairing the barrier is a more satisfying job knowing that the barrier prevented severe injury or even death.
- Warrants for installation of median cable barrier tend to a severe crash history. Such a large potential for installation forces decision makers to take care of worst cases first.
- States are still in the learning process. Information gathered in this Scanning Tour provided valuable knowledge on system characteristics, performance, and maintenance.
- This Scanning Tour has been very useful to guide the participant states in all aspects related to the use of high-tension cable systems in their roadway systems. Similar scanning tours are recommended in the future for addressing particular issues in transportation.

In addition to those lessons learned, more experience and data is needed to draw conclusions or make improvements on the following aspects:

- The in-service performance evaluation (ISPE) for any system has not been completed. Performance in the long run is not known.
- Results from long-term benefit-cost analyses are not yet known.
- Differences in performance and long-term maintenance issues between cable systems (3-cable and 4-cable systems) are not completely clear.
- Designs for cable systems at points of interaction with other structures such as guardrail, bridge piers, or sand barrels, are not completely standardized.
- Practices dealing with crossover requirements from first responders and crossover gaps are still being improved.
- Guidelines for optimum location of cable barriers in various types of median widths and slopes need to be developed.
- It is not known how updates in NCHRP 350 criteria can affect the systems and their usage.
- A new national guideline for median barrier warrants by AASHTO is anticipated. The guideline is a tool that can help states in identifying their needs for median barriers. It will also provide States the flexibility to customize their warrants based on local data and factors such as highway systems, crash history, politics, and public opinion.

List of Appendices

1. Participants in Meetings
2. Report “Ohio DOT Field Visits to Cable Median Barrier Projects”. Ohio DOT
3. Selected Photographic Material – NUCOR Marion Steel Inc. plant
4. Cable Locations in Oklahoma City Metro Area
5. Crash report – Cable Locations in Oklahoma City Metro Area
6. Selected Photographic Material – Oklahoma
7. Report “Brifen Wire Rope Safety Fence Final Report”. Ohio DOT
8. Internal letter Oklahoma DOT – Oklahoma DOT Experience with Brifen WRSF on Lake Hefner Parkway in Oklahoma City
9. Questionnaire responses – Oklahoma
10. Special Specification 5084 – Cable Barrier System (TXDOT)
11. Selected Photographic Material – Texas
12. Plans of Proposed State Highway Improvement - Federal Aid Project STP 2005(792)SFT – Details for Brifen WRSF and CASS
13. Maintenance / Repair Log Sheet (TXDOT)

Appendix 1

Participants in Meetings

Date: August 29, 2005

Time: 2:30 PM EDT

Place: Ohio DOT, Columbus, OH

Name		Organization
David	Piper	Illinois DOT
Deanna	Maifield	Iowa DOT
Chris	Poole	Iowa DOT
Gary	Dirlam	Minnesota DOT
John	Hanzalik	Minnesota DOT
Juan	Medina	University of Illinois
Peter	Amakobe	Wisconsin DOT
John	Bridwell	Wisconsin DOT
Dean	Focke	Ohio DOT
Mark	Hatfield	Ohio DOT
Joe	Glinski	FHWA Ohio

Date: August 30, 2005

Time: 9:00 AM EDT

Place: NUCOR Marion Steel Inc. plant, Marion, OH

Name		Organization
David	Piper	Illinois DOT
Deanna	Maifield	Iowa DOT
Chris	Poole	Iowa DOT
Gary	Dirlam	Minnesota DOT
John	Hanzalik	Minnesota DOT
Juan	Medina	University of Illinois
Peter	Amakobe	Wisconsin DOT
John	Bridwell	Wisconsin DOT
Dean	Focke	Ohio DOT
Rick	Mauer	NUCOR Marion Steel, Inc.
Joe	Glinski	USDOT - FHWA

Date: August 31, 2005

Time: 8:00 AM CDT

Place: Oklahoma DOT, Oklahoma City, OK

Name		Organization
David	Piper	Illinois DOT
Deanna	Maifield	Iowa DOT
Chris	Poole	Iowa DOT
Gary	Dirlam	Minnesota DOT
John	Hanzalik	Minnesota DOT
Juan	Medina	University of Illinois
Peter	Amakobe	Wisconsin DOT
John	Bridwell	Wisconsin DOT
Faria	Emamian	Oklahoma DOT
E.W. "Red"	Miller	Oklahoma DOT
Nabeel	AbuSadah	USDOT - FHWA
Huy	Nguyen	USDOT - FHWA

Date: August 31, 2005

Time: 1:00 PM CDT

Place: Brifen USA, Oklahoma City, OK

Name		Organization
David	Piper	Illinois DOT
Deanna	Maifield	Iowa DOT
Chris	Poole	Iowa DOT
Gary	Dirlam	Minnesota DOT
John	Hanzalik	Minnesota DOT
Juan	Medina	University of Illinois
Peter	Amakobe	Wisconsin DOT
John	Bridwell	Wisconsin DOT
Faria	Emamian	Oklahoma DOT
Richard	Butler	Brifen USA, Inc.
Jerry	Emerson	Brifen USA, Inc.

Date: September 1 and 2, 2005

Time: 1:30 PM CDT

Place: Texas DOT, Weatherford, TX

Name		Organization
David	Piper	Illinois DOT
Deanna	Maifield	Iowa DOT
Chris	Poole	Iowa DOT
Gary	Dirlam	Minnesota DOT
John	Hanzalik	Minnesota DOT
Juan	Medina	University of Illinois
Peter	Amakobe	Wisconsin DOT
John	Bridwell	Wisconsin DOT
-----	-----	-----
Jimney F.	Bodiford	Texas DOT - Fort Worth District - Weatherford Area office
Alan B.	Donaldson	Texas DOT
John	Cordary	Texas DOT
Jackie R.	Baker	Texas DOT

Appendix 2

Ohio DOT Field Visits to Cable Median Barrier Projects (4/11/05, summary added 4/13)

ODOT's Office of Roadway Engineering Services organized several field visits during February and March 2005 to identify post construction concerns for the first wave of cable median barriers installed in Ohio. Representatives from Central Office's Roadway Engineering, Production, and Safety & Mobility offices, along with district, manufacturer, contractor and FHWA personnel were invited to each meeting.

The purpose of the field visits were an effort to ascertain and monitor any design, construction, maintenance and performance issues so that these lessons could be applied to future projects.

For background information, cable barriers are being considered as standard median protection for ODOT. This is due to the apparent increase in cross median accidents throughout the state.

Even on the national level, AASHTO and NCHRP have been working to develop new Median Barrier Warrants to replace AASHTO's Roadside Design Guide Figure 6.1 (published in ODOT's Location and Design Manual, Volume 1, as Figure 601-2). Because national guidance in providing states with updated guidelines is lagging, several states have implemented their own warrants. Within ODOT, the offices of Safety & Mobility and Roadway Engineering are working together to develop guidelines for Ohio. According to one analysis approximately 500 miles of ODOT Interstate system is a candidate for cable installation.

Several states have had a median protection program in place for at least a few years. The states that have been leading the way on median protection have used generic cable (known as US Customary) because of a lack of other suitable products. This generic cable has been in use by the state DOT's for several decades for roadside applications. Since this product has some major drawbacks, it never really gained favor over standard w-beam guardrail in Ohio. However, ODOT itself has installed the product once, in the median of LAK-90 in the early 1990's.

ODOT accepted existing national guidance on Median Barrier Warrants until a rash of accidents on Interstate 75 north of Cincinnati. Within a 14-month period starting in October 2001 there were 11 fatal cross median accidents. Investigation of each accident report shown no single factor was involved; all of them seemed to be unique. ODOT responded by installing a new and revolutionary type of cable system in this stretch of interstate. It is a tensioned cable system and the product is attractive because it seems to have overcome the biggest concern of the generic system: tensioned cables hold their height after an impact and were poised for a second impact without immediate repair.

The system chosen was Brifen's Wire Rope Safety Fence. It is a product that has been in use for 15 years exclusively outside of the United States (except for it's first US installation, in Oklahoma). Since some of the steel components were only available from the Great Britain, ODOT obtained FHWA approval to install it here. Brifen components are now made in the USA.

Three other proprietary cable systems have now been accepted by FHWA as having met NCHRP Report 350 crash testing criteria. They are the Trinity CASS, Marion Steel SafeRoads and the Safence system. (Safence is not yet made from American materials and is not discussed here.)

ODOT is currently of the position that each of these products performs in a similar manner

during impacts and therefore the three products should be bid as equals. However, this position does not account for any installation, repair or maintenance concerns. The field visits were an effort to determine if it is a valid assumption, or if one product stands out as being better and should be recommended.

Ohio is the only state which has each of the three proprietary cable systems installed, allowing us a unique position to compare the products. During the visits, the groups looked at the design, construction, maintenance and performance issues with each barrier.

The three locations visited are Brifen (BUT/WAR 75), Marion Steel (FRA 270/315) and Trinity (LOR 90). Each system and field visit is described below.

Brifen WRSF

Central Office staff met with District 8's Planning, Construction and Maintenance, FHWA's Joe Gliniski, and Brifen's Richard Butler on March 7 at District 8. Brifen's 14 mile system was installed in 2003 and its performance had actively been tracked as part of FHWA's approval of the foreign product in 2002. In fact, this office submitted the first of three yearly In-service Performance Evaluation reports to FHWA just prior to the visit. The report concludes the system is working as expected, although it is prudent to continue to gather data for two more years.

The biggest issue raised was that of a recorded accident occurring on January 4, 2005 which destroyed 14 posts, a significant accident on a tensioned system. The accident was caused by a passenger car spinning on wet pavement (a witness said 80 mph), hitting the cable on the near side of the ditch. Somehow the vehicle penetrated the cable, and wound up on the other traffic lanes, causing a second accident. One non-incapacitating injury was reported. In the field visit no one could say for sure if the cable was the cause of the penetration or a fluke of the accident.

The Brifen cables weave through every post, providing additional tension. However, in an accident taking out so many posts, the weave is removed allowing slack in the cable to the point where the cables sagged. The cables sagged to approximately one-half of the correct height. For any cable system the most important key is for the cables to remain at the correct height. A tensioned system can lose its tension and still perform satisfactorily (it becomes a defacto generic system at that point) but if the cables are not at the correct height the system may not engage, or capture, the impacting vehicle.

At this particular accident site, the posts were still missing and the cable still sagged a full two months after the accident. The time between repairs was disconcerting.

District 8 forces perform repairs on this system, and the process they use to repair may contribute to the delay. During design most posts were driving into the ground but as an experiment 2 miles of the 14-mile system were installed with concrete foundations for socketed posts. Socketed posts were offered by the manufacturer as an easier way to repair a damaged post and a segment was installed to test this suggestion. After installation, the District immediately saw the benefits of the socketed posts in accidents because of the ease of repair. The District made the decision to upgrade all impacted posts with a concrete socketed foundation. These types of repairs necessitate extra work because of the concrete involved. Due to winter weather the median was not able to support the equipment needed and the District

was not able to repair the affected site. If the District had just driven in new posts to replace the damaged ones, the repairs may have been able to be done sooner.

A complicating factor was that this system had previously been repaired at this very location using one of these concrete foundations. In the January accident one of these foundations was pulled completely out of the ground. On inspection it did not appear to have any influence on the subject accident. But this particular foundation did not appear to be constructed as to manufacturers specification (12" diameter, 36" reinforced foundation).

Marion Steel SAFEROADS

Roadway Engineering Services, Production, and Safety & Mobility staff met with FWHA's Joe Glinski and Marion's Kevin Mally and Rick Mauer, at the site on February 8, 2005.

Marion's 12 mile system was installed in during several months in the last half of 2003. The contractor had difficulties developing a process for installation, and once that was done construction went at a smoother pace except for problems encountered by the presence of rock near the surface.

Random stops at various locations showed no obvious problems. At unrepaired accident locations it was evident that for the most part the posts sheared at the ground line and slid down the cable to a final resting point, as designed. At accidents sites, the cable seemed to remain in tension and the cables did not visually sag.

However, on March 4 this section was called to an emergency meeting at the I-270 construction office in Grove City. District 6's Construction and Maintenance had called Marion Steel's Steve Conway and Rick Mauer along with the contractor MP Dory's Tom Kuhn to discuss the Construction Engineer's belief that the TTI anchor foundations on the Marion Steel cable project were poorly designed and were moving, with the result of the terminal anchor being pulled out of the ground and a subsequent loss in cable tension in about 5 individual posts of the 35 anchors sets (3 posts each). The TTI anchor is a third-party product and is also used with the Trinity CASS cable. Each anchor foundation is a 2' by 5' deep reinforced concrete dead man weight. To their credit, Marion Steel did agree to redesign the anchor and to offer ODOT a retrofit design for the majority of anchors that did not exhibit problems. This problem is independent of the cable and is being handled separately.

Marion Steel brought out a prototype portable tension meter for the contractor. While running the tension tests on the system, it was observed several cables were rather loose, not up to the ideal 5,600 pounds of tension at 70 degrees F. Some locations were less than 3,000 pounds of force. There may be many explanations for this as in method of taking the force, an uncalibrated meter, and the residual slack of a non-pretensioned system.

On March 18, this office was again called to the field by reports of line post foundations being pulled out of the ground during accidents. Upon inspection of two accident sites that the 3 foundations were damages in a 9-post hit, and 2 were damaged in a 5-post hits. The posts did not shear as designed but were bent over from the force of the impact. The channel design may have provided too much resistance and forced the socket tube to shatter the reinforced concrete foundation. This problem has occurred yet again and is actively being investigated by ODOT.

Trinity CASS

Roadway Engineering Services, Production, and Safety & Mobility staff met with District 3's

Production and Maintenance staff, FHWA's Joe Glinski, Trinity's Gwen Samuels, Robin Cera, and Robert Takach, and Lake Erie Construction's Ray Chapin on March 17 at ODOT's Avon Outpost. Trinity's 3 mile system was completed in October 2004, so its short time and length of exposure to traffic have not given us much data to observe. The system had never been repaired since its installation and there were two locations where 4 posts were missing. The cable remained in tension and the slack was minimal. And the asphalt mow strip led the system to have clean lines and little of the debris noticed at the other cable sites.

The group went to another location where only one post was damaged and replaced it with a new socketed post and reset the cable. Total repair time was under 5 minutes.

The group found a very recent cross median hit where the vehicle crossed the ditch line and struck the backside of the cable at the edge of the opposite shoulder, damaging another 4 posts. From the tire marks, the vehicle apparently had hit the cable at a relatively high angle and was clearly headed for the opposing traffic lanes when the cable redirected it. The CASS cables remained in tension and was ready for another impact without needing repair.

The TTI anchors on this project seemed to be solid and not moving.

Summary

The associated table summarizes the results of the visits to each of the three proprietary systems. Information on an ODOT installation of a generic 3-strand cable is also listed for comparison. Each of the proprietary systems seems to be performing to NCHRP Report 350 criteria. There is ample evidence all of the systems are preventing crossover accidents.

The intent of the field visit was to identify any potential issues to monitor. Found issues and current disposition of those issues are noted in the table.

Although one of the goals of the field visits was to determine if one system truly out performs the others, many factors complicated the picture and we cannot make such a recommendation at this early juncture. Design placement, Construction issues, Maintenance decisions, short length and duration of exposure prevent us from comparing the systems against each other. For example, ODOT is gathering solid ISPE information only on the Brifen WRSF. The Marion Steel SafeRoads cable installation is very close to the office, allowing perhaps closer scrutiny than the other systems. The Trinity CASS is of shorter length than the others leaving it with less data to compare. In the future, we will attempt to overcome this problem, so a valid comparison may be attempted.

SUMMARY OF CABLE PRODUCTS (Prepared 4/11/05)				
System	Brifen	Marion	Trinity	Base (generic)
----- PRODUCTS -----				
Description	4 cable woven, tensioned and prestretched	3 cable tensioned but not prestretched	3 cable tensioned and prestretched	3 cable un-tensioned and not prestretched
Product History	3000 km of use 20 foreign countries	new system, based on well known and often used frangible sign posts.	new system to USA, but modified from an existing European system	generic cable has been in use in US since 1960's but not an ODOT standard
ODOT Installation	BUT/WAR 75 June 2003 (second in USA)	FRA 270/315 Oct. 2004 (first in USA)	LOR 90 Oct. 2004 (sixth in USA)	LAK 2 1991 (standard used throughout US)
Length of Ohio's Installation	14 miles	12 miles	3 miles	12 miles
Post spacing and crash tested deflection (at that post spacing)	10' 6" spacing 7.9' deflection	6' 6" spacing 6.5' deflection	10' 0" spacing 7.9' deflection	16' 0" spacing 11.2' deflection
Application	on one side of median slope	at edge of wide paved shoulder on one side	at edge of wide paved shoulder on one side	on one side of median slope
Approx. # of hits recorded	160 (6.5 hits/mile/year)	30 (5.0 hits/mile/year)	10 (6.7 hits/mile/year)	n/a
----- ISSUES TO MONITOR -----				
Issues	<p>1) A penetration of unknown reason has been recorded. Two additional years of ISPE will watch this.</p> <p>2) Cable sagging in severe hits. District will begin to include information on ISPE.</p> <p>3) District decision to replace driven posts with concrete socketed foundation affects timeliness of repair. Topic is being discussed by CO and District Maintenance.</p>	<p>1) Replacing of problem anchor foundations.</p> <p>2) Retrofitting of the remaining anchor foundation to the Project Engineer's satisfaction.</p> <p>3) Redesign of damaged line post foundations.</p> <p>4) Keeping watch on the cable tension.</p> <p>Mfg. is working on but has not yet offered fix for anchor or line posts.</p>	<p>1) Anchor system is the same as on the Marion Steel system and may be vulnerable to movement as well.</p> <p>District will alert CO if problem arises.</p>	<p>1) D-12 Maintenance wrote in 2000 of the problems in maintaining the cable and keeping parts.</p> <p>D-12 then recommended replacing the cable with Type 5 guardrail.</p> <p>Cable is still in place as no project has coincided with this work.</p> <p>Widening project is programed.</p>
----- CONCLUSIONS FROM FIELD VISITS (Generic system not visited) -----				
Performance Conclusions	System performing to NCHRP Report 350 standards	System performing to NCHRP Report 350 standards	System performing to NCHRP Report 350 standards	System conforms to previous crash test criteria, NCHRP Report 230
Summary	Best accident data, longest evaluation time, proven system elsewhere, extra cable, woven. System seems to be proving itself beneficial.	Construction issues, first substantial installation for product, so mfg's. installation and repair manual being written after the fact from our experiences.	Construction went smoothly and observed repair was very easy. Looks to be a good system, but the length, and thus exposure to accidents, is limited.	District says cable needs immediate attention after an accident and parts are difficult to obtain.

Appendix 3

Selected Photographic Material – NUCOR Marion Steel Inc. plant



1. Melting process in electric arc furnace



2. Melt steel ready to be poured and cast



3. Steel cooled down with water.
Before casting



4. Continuous billet casting



5. Billets cut to length at the end of the line



6. Stored billets ready to be rolled



7. Posts are stored after rolling



8. Holes are punched and posts are ready to be distributed



9. U.S. High Tension Cable Installation



10. End Treatment



11. Anchors



12. Turnbuckle




13. Tension meter



14. U-shaped bolts to fix cable height

Appendix 4

CABLE LOCATIONS IN THE OKC METRO AREA



Appendix 5

Cable Locations in OKC Metro Area

Traffic Engineering Division - Oklahoma Department of Transportation

Brifen - Hefner Parkway/SH-74 (Installed 9/1/01)						
Crossover Before			Crossover After			Reported Barrier Hits Since Installation
Time Frame			Time Frame			
9/1/96 to 8/31/01			9/1/01 to 7/31/05			
Fatal	Injury	PD	Fatal	Injury	PD	Total
6	10	4		1	1	132

Reductions	83%	90%	75%
------------	-----	-----	-----

Brifen - I-35 (Norman) (Installed 9/30/04)						
Crossover Before			Crossover After			Reported Barrier Hits Since Installation
Time Frame			Time Frame			
10/1/99 to 9/30/04			10/1/04 to 7/31/05			
Fatal	Injury	PD	Fatal	Injury	PD	Total
6	16	9	0	0	1	21

Reductions	100%	100%	89%
------------	------	------	-----

Safence - I-35 (McClain County) (Installed 9/30/04)						
Crossover Before			Crossover After			Reported Barrier Hits Since Installation
Time Frame			Time Frame			
10/1/99 to 9/30/04			10/1/04 to 7/31/05			
Fatal	Injury	PD	Fatal	Injury	PD	Total
1	5	1	0	0	0	3

Reductions	100%	100%	100%
------------	------	------	------

Cass System - I-35 (McClain County) (Installed 8/26/05)						
Crossover Before			Crossover After			Reported Barrier Hits Since Installation
Time Frame			Time Frame			
8/1/0 to 7/31/05			No Data Available			
Fatal	Injury	PD	Fatal	Injury	PD	Total
3	1	3	No Data Available			No Data Available

Appendix 6

Selected Photographic Material – Oklahoma



1. Brifen Post



2. Brifen Installation on SH-74



3. Detail Brifen weaving cable




4. End treatment protected with sand barrels



5. Top view Brifen TL-3 post




6. Concrete foundation and plastic extruder



7. Turnbuckle on Brifen installation



8. Brifen Turnbuckle -Detail



9. Brifen system on I-35



10. SAFENCE system on I-35



10. Reinforced socket – Brifen



11. TL-3 posts - Brifen



11. TL-3 post – Brifen



12. TL-4 post – Brifen



13. TL-3 extruder + TL-4 post + plastic cap with reflectors

Appendix 7



BRIFEN WIRE ROPE SAFETY FENCE FINAL REPORT

BRIFEN WIRE ROPE SAFETY FENCE FINAL REPORT



Oklahoma Department of Transportation
Traffic Engineering Division
200 N.E. 21st Street
Oklahoma City, OK 73105

By: Faria Emamian, P.E.
March 2003

Acknowledgments

Thanks and appreciations to the following individuals and groups for their assistance and guidance:

Harold Smart, P.E.	ODOT, Traffic Engineering Division
Red Miller, P.E.	ODOT, Traffic Engineering Division
Stanley Greene	ODOT, Traffic Engineering Division
FHWA	Oklahoma Division
Jerry Emerson	BRIFEN*USA
Steve Wells	Mid State Traffic Control Construction
Graham Sharp	BRIFEN

DISCLAIMER

This document is prepared under sponsorship of the Oklahoma Department of Transportation. The State of Oklahoma assumes no liability for its contents or use thereof.

The contents of this report reflect the results of experimental use of the BRIFEN Safety Wire Rope System in the State of Oklahoma. This report does not constitute a standard, specification, or regulation of usage of the BRIFEN Safety Rope System.

TABLE OF CONTENTS

Section		Page
1.0	INTRODUCTION	3
2.0	DESIGN & CONSTRUCTION	4
2.1	Median Barrier Options	4
2.2	BRIFEN Wire Safety Rope	4
2.2.1	Introduction	4
2.2.2	Usage	5
2.2.3	Initial System Installation Costs	5
2.2.4	BRIFEN WRSF Design Details	7
2.2.5	Advantages and Disadvantages	9
2.3	Lake Hefner Parkway Experience	10
2.3.1	Choosing BRIFEN WRSF	11
2.3.2	Experimental Project	13
3.0	COLLISION REPORTS AND FINDINGS	14
3.1	Historical Collision Summaries	14
3.2	Impacts	15
3.2.1	Analysis of Impacts before Installation	15
3.2.2	Analysis of Impacts after Installation	15
3.2.3	Fatalities and Injuries	16
4.0	MAINTENANCE AND REPAIR	18
4.1	WRSF Maintenance and Repair Costs	18
4.2	Cost Analysis	19
4.3	Cable Barrier Studies from Other States	20
4.4	Repairs	20
5.0	CONCLUSIONS AND RECOMMENDATIONS	20
	APPENDIX A: COLLISION RECORDS	22

1.0 INTRODUCTION

Lake Hefner Parkway (LHP), a section of State Highway 74 in northwest Oklahoma City, is a six-lane freeway connecting to I-44 at the south end and extending north to the Kilpatrick Turnpike for a distance of approximately seven miles. Traffic volume in 2000 was 108,000 vehicles per day and is increasing. The grassy center median varies in width from 36' to 42', with no initial installation of a cross-over barrier. There is no lighting or overhead signing along much of the LHP length since it traverses an environmentally sensitive area beside a large reservoir, Lake Hefner. Local residents did not want their view of the lake compromised, and Oklahoma Department of Transportation (ODOT) complied with these demands.

However, after opening to traffic in 1991, this highway began experiencing a high number of median cross-over collisions and fatalities. Between June 1, 1997, and May 31, 2000, 185 collisions were reported, including 11 cross-overs which resulted in four fatalities. This increasing number of cross-over collisions along with their high rate of severity prompted ODOT to research possible design alternatives to prevent or reduce the severity of these crashes.

The options considered included concrete median barriers, strong-post guardrail barriers and cable barriers. The design chosen was a British cable barrier system known as the BRIFEN Wire Rope Safety Fence (BRIFEN WRSF), which had never been used in the United States and, at the time, had not been approved as meeting the requirements of the National Cooperative Highway Research Program Report 350 (NCHRP-350). Roadside features used on the National Highway System (NHS) of which LHP is a part must meet NCHRP-350 requirements. Also, at the time, BRIFEN WRSF was fabricated using foreign steel which meant that it did not comply with the "Buy America" regulations. These and other issues were discussed with the local Federal Highway Administration (FHWA) Division office, which agreed with ODOT that, based upon its reported excellent performance worldwide, BRIFEN WRSF should be tried on an experimental basis by installing a section along the LHP.

A two-phase experimental project was initiated by ODOT and approved by the FHWA in August of 2000. The first phase, a 1000' section, was installed in August of 2000 for study and evaluation purposes.

During the winter of 2000 the experimental section was impacted several times, performed well, and was easily repaired. It was also considered aesthetically pleasing and did not cause snow drifts. The effectiveness of this section of BRIFEN WRSF warranted installation along all seven miles of LHP for further study and analysis. This document will present findings and evaluations from these experimental sections of BRIFEN WRSF regarding its effectiveness in preventing cross-over collisions, as well as its installation, maintenance and repair costs, and recommendations for future uses of the system.

2.0 DESIGN & CONSTRUCTION

2.1 MEDIAN BARRIER OPTIONS

ODOT has primarily used only two types of barriers for median applications to prevent cross-over crashes. Concrete "New Jersey" shape median barriers have been used predominately in the past, along with a few "single-slope" median barriers used more recently. The "F" shape median barrier will be ODOT's primary concrete barrier in the future. Steel "W-beam" barriers have had limited use for median applications, but are primarily used for bridge end, pier, and side slope shielding. These systems are designed to accommodate NCHRP-350 Test Level Three (TL-3) vehicles, such as small 820 kg (1800 lb) passenger cars up to 2000 kg (4500 lb) pick-up trucks which commonly travel through Oklahoma.

Another barrier, available to ODOT but never used, was the three-cable generic design used by states such as Arizona, New York, North and South Carolina, South Dakota and others. ODOT has never used a three-cable barrier due to the high level of maintenance required and the fact that this type of cable barrier typically falls to the ground after a hit, unable to sustain shielding until it is repaired. Several states (Arizona, New York, North Carolina, Oregon) have reported these types of problems. Another aspect of the three-cable barrier is that it deflects 3.4 - 3.7 m (11' to 12') when impacted, limiting its usage in areas where obstructions are close to the roadway. ODOT determined these characteristics were unacceptable for use on a high-volume traffic freeway such as the LHP.

The other option was the BRIFEN WRSF, which deflects much less (6' to 8'), remains upright after typical hits, and can handle additional hits before repair. It is also easy and quick to repair and is now a NCHRP-350 approved system at TL-3.

2.2 BRIFEN WIRE ROPE SAFETY FENCE

2.2.1 Introduction

The BRIFEN WRSF, originally developed by Briton, Ltd. of the United Kingdom (UK), is a four-rope system that, according to the manufacturer, has been in successful service since 1989 in over 30 countries around the world.

The BRIFEN WRSF used on the LHP consists of four pre-stretched wire ropes supported by weak steel posts and anchored at each end to concrete ground units. Since some posts can be damaged with every impact, using the socketed design allows posts to be replaced very quickly by one or two workers with only hand tools and no heavy equipment. Driving the posts would reduce initial costs slightly; however, maintenance costs would increase, requiring more time to drive each replacement post and possible lane closures during the repair.

2.2.2 Usage

BRIFEN WRSF consists of pre-stretched wire ropes that are highly tensioned after installation and are attached to weak steel posts that are designed to bend over and release the ropes on impact. As is typical for cable barrier systems, BRIFEN WRSF allows snow to pass through rather than drifting and building up against the barrier, as is common with a concrete or W-beam barrier. BRIFEN WRSF can be used in locations where obstructions are closer than could be tolerated by the three-cable design.

With its standard 3.2 m (10.5') post spacing, deflection during TL-3 tests with a 2000 kg (4500 lb) pickup was only 2.4 m (7.8'), as compared to typical three-cable barrier deflections of 11' to 12'. Computer simulations have shown that BRIFEN WRSF deflections could be reduced to approximately 1.2 m (3.9') if post spacings of 1.5 m (4.9') are used. All cable systems must be used where there is enough lateral clearance behind the system to allow for uninterrupted deflection during an impact.

With its standard post spacing, BRIFEN WRSF can be used in medians 4.9 m (16') or more in width without risk of vehicles crossing into opposing lanes, assuming the system was installed in the center of the median.

Many locations worldwide have used BRIFEN WRSF in medians with far less than minimum median width and reportedly have performed well. No cross-over collisions have ever been reported where BRIFEN WRSF was in place.

2.2.3 Initial System Installation Costs

Costs comparisons for BRIFEN WRSF and other commonly used median barrier systems are listed in Table 2.1. The BRIFEN WRSF initial cost is somewhat higher than the three-rope generic system, but less expensive than traditional W-beam systems. Concrete barriers are far more expensive.

Table 2.1: Initial Cost Comparisons of Median Barrier Types

Median Barrier Type	Cost per mile
BRIFEN WRSF, Driven Posts & Anchors	\$68,000
BRIFEN WRSF, Socketed Posts & Anchors	\$84,000
Three-Cable U.S. Generic Fence, & Anchors	\$50,000
Double-Face W-beam Guardrail	\$105,000
Concrete Median Barrier	\$500,000

Cable barrier systems are typically less expensive due to their relatively light-weight design. Their metal posts are much smaller than W-beam posts, since they are intended to collapse upon impact, and little or no grading or earthwork is needed. Concrete barriers, by contrast, must usually be placed on a concrete or asphalt base with modified drainage features and extra paved shoulder widening or lane additions to fill the space between the barrier and the travel lanes. For these reasons the cost of concrete barriers tends to be significantly higher. This is especially true for wide medians.


Overall long-term costs for the above options are difficult to project; however, if vehicle damage and costs for severe injuries were included, W-beam and concrete barrier costs would be considerably higher when compared to cable systems. Maintenance costs for concrete barriers are low since they are rarely damaged enough to need repairs. This is not the case for W-beam barriers, which are maintenance intensive.



2.2.4 BRIFEN WRSF Design Details


The BRIFEN WRSF consists of four 19 mm (3/4") pre-stretched galvanized wire ropes supported by "S" shape galvanized steel posts. The ropes along the necessary length are not directly attached to the posts. The top rope is 720 mm (28-3/8") above ground and is placed in a slot in the top end of the posts. The two intermediate ropes are 675 mm (26-9/16") above ground and are supported by hard plastic pegs on either side. These two ropes alternate sides from post to post. This patented "weaving" contributes to the small amount of deflection, when compared to the three-cable generic system, and helps to retain rope tension during an impact, acting as a "mini-anchor". The fourth rope, 510 mm (20-1/16") above the ground, rests on the same type of plastic peg and also weaves from side to side between posts.

There are two options for installing the BRIFEN WRSF support posts. They can either be driven in or placed into socketed concrete foundations. Because some posts will be damaged with every impact, using the socketed design allows the bent posts to be easily replaced. This can be done by one worker with only simple hand tools; no heavy equipment is needed. Driving the posts reduces the initial cost, but maintenance costs are increased, since driving each replacement post requires more time and possible traffic-lane closures during repair.




WSRF Post Details





Plan & Profile Views of BRIFEN WRSF



2.2.5 Advantages and Disadvantages

The BRIFEN WRSF has several advantages over the three-cable weak-post barrier currently used in the U.S. The initial construction cost of the BRIFEN WRSF is somewhat higher than the three-cable system, but maintenance and repair costs are less for the BRIFEN WRSF system when compared to the three-cable, weak-post barrier or W-beam guardrail. This is primarily due to the small amount of BRIFEN WRSF typically damaged during an impact.

The three-cable system is notorious for having re-tensioning problems due to "construction stretch" when impacted. Many times all of the cable between the anchors will fall to the ground and must then be re-tensioned after the posts are replaced, which means that the barrier is not capable of re-directing another vehicle. The ropes used in the BRIFEN WRSF are pre-stretched, then highly tensioned during installation, and, after most impacts, will continue to function and sustain additional hits prior to being repaired. Thus, BRIFEN WRSF has largely eliminated the "cable-on-the-ground" problem. The U.S. three-cable barrier uses either small steel I-beams or steel channel posts which are typically driven into the ground. These are time consuming to replace compared to the BRIFEN WRSF posts, especially if the posts are placed in socketed foundations. Replacing a few posts in the BRIFEN WRSF system takes one or two workers only a few minutes, requiring only minimal traffic delays. The ropes typically never need re-tensioning due to traffic impacts.

In the event that the ropes need to be loosened after a collision due to vehicle entanglement, it is easily done with the rigging screws (turnbuckles) which are spaced approximately every five hundred feet. Another advantage is the smaller deflections occurring with the BRIFEN WRSF system during an impact. Maximum deflection in TL-3 length of need tests was 2.4 m (7.8'), whereas the three-cable system deflects approximately around 3.4 to 3.7 m (11'-12'). An additional advantage of BRIFEN WRSF over the three-cable system is that it only needs an anchor at each end, regardless of the length of the section of BRIFEN WRSF. This is due primarily to the patented weaving of the ropes such that each post acts as a "mini-anchor" due to the friction generated as the ropes go around the sides of the posts.



102.3 LAKE HEFNER PARKWAY EXPERIENCE

Lake Hefner Parkway is a seven-mile section of SH-74, a six-lane divided freeway with a 36' to 42' median, located in northwest Oklahoma City. The LHP runs north from the 39th Expressway to the Kilpatrick Turnpike, and serves as a primary route for business commuters traveling from the surrounding housing communities and those further north into the metro area. In 2000, the average annual daily traffic was 108,000 vehicles per day. Approximately four percent of this traffic consisted of trucks.



2.3.1 Choosing BRIFEN WRSF

Another aspect discussed was safety to the driver and passengers within the vehicle colliding with the barrier. A concrete barrier is very rigid. Due to the number of cross-over collisions on the LHP, ODOT staff requested the approval of the Transportation Commission to research preliminary designs for a median barrier along the seven-mile extent north of 39th Street. Several alternatives were discussed along with the BRIFEN WRSF, which had never been used in the U.S. and had not been approved by the FHWA for use on the National Highway System. This product was brought to ODOT's attention by a safety engineer of the Federal Highway Administration (FHWA) Oklahoma Division Office, who had seen it while traveling in other countries.

The other alternative designs considered were an ultimate design consisting of added lanes and a concrete median barrier, an interim design of a concrete barrier on one shoulder, a strong-post guardrail, and the three-cable system currently being used in the U.S.

One consideration was cost, including initial and maintenance. The ultimate design, including added lanes and concrete barrier was the most maintenance-free, but the most expensive. The initial cost for this design was estimated at approximately \$11.3 million, with low maintenance costs, since damage to concrete barriers is usually minimal. Concrete barriers located along one shoulder was also considered and was estimated at approximately \$3.4 million with similar, low maintenance costs. Strong-post guardrail was estimated to cost approximately \$1.5 million, with high maintenance costs, requiring replacement of both rail and posts after most high speed impacts, and requiring lane closures and other traffic control considerations.

The three-cable U.S. system was estimated to cost \$409,142 but would likely have high repair costs due to replacing posts and re-tensioning the cables, and the need for frequent inspections to detect damaged sections which would be ineffective during subsequent hits until repairs could be made.


The BRIFEN WRSF system was estimated to cost \$675,517, plus some additional costs for asphalt weed-control paving. This initial cost was higher than the three-cable U.S. system, but the maintenance cost was expected to be much lower; and the BRIFEN WRSF could be expected to remain at near-design height before being repaired. Considering both initial costs and long-term maintenance costs, the BRIFEN WRSF was considered to be the most efficient alternative.

Another consideration was effectiveness. Concrete barriers are almost 100% effective in that they usually will not allow a vehicle to cross the median. Guardrails are also generally effective; but, after an impact, will not work until repairs are made. Similarly, the U.S. three-cable system will stop most impacts, but, once hit, the low-tension cable falls to the ground making the whole stretch between anchors vulnerable to crossovers. Also, many more end anchors would be required since two anchors are required approximately every 1,000'. Frequent inspections are needed along with timely repairs to effectively maintain the system. The BRIFEN WRSF could be expected to eliminate most of these problems. ODOT was advised by the manufacturer and other agencies that impacts had occurred from many different angles, directions, and speeds and there had never been a cross-over incident reported with the system in place. In addition, after

being impacted, the high tension ropes usually stayed in place and continued to prevent secondary crossovers. In contrast, impacts with the concrete median barrier can do great damage to vehicles and cause serious injuries or death. The strong-post guardrail is semi-rigid but can still place large forces on vehicle occupants and cause major damage to vehicles. The three-cable system and the BRIFEN WRSF are the least likely to injure passengers because of the "soft," gradual deflection typical of the cables/ropes. With the use of the BRIFEN WRSF system, agencies reported that under many circumstances, when the fence is hit the vehicle is only slightly damaged. In these instances the driver vacates the collision site and leaves the repair cost to the public agencies. Both the three-cable and the BRIFEN WRSF systems do not deflect the vehicle back out into traffic. Finally, cable barrier systems do not block passage of wildlife.

The final consideration was aesthetic. The BRIFEN WRSF was considered by ODOT's design staff to be more visually pleasing and acceptable to the surrounding community than any of the other alternatives.

After comparing the advantages and disadvantages, the BRIFEN WRSF was determined to be the best alternative. Its initial cost was considered reasonable, with maintenance and repair simple and inexpensive. Evidence and testimony showed the system to be very effective at preventing vehicles from crossing over medians, reducing the degree of injuries, and continuing to provide post-hit protection.



2.3.2 Experimental Project

Once ODOT chose to use the BRIFEN WRSF on the LHP, FHWA approval had to be requested because this system had not yet been approved for use on the National Highway System. During this time, BRIFEN WRSF had been attempting to get the system approved as meeting NCHRP-350, but in the interim the FHWA Oklahoma Division approved the installation of a 1000' section (donated by the BRIFEN Company) as Phase I of an experimental project. Shortly after the initial section was in place, BRIFEN WRSF was approved by FHWA as meeting NCHRP-350 Test Level 3 requirements and work continued on the development of TL-3 end anchors. The FHWA maintained that the experimental project could be installed as long as the end anchors were shielded from traffic or placed beyond the clear zone.

In September 2000, the manufacturer partnered with Midstate Traffic Control, Inc. of Oklahoma City and installed the test section where both end anchors could be located near existing overhead sign structures where protective sand barrel crash cushions were already in use.

During the next few months the section was hit four times and performed extremely well each time. Since the Phase I test was considered successful, Phase II was installed during summer 2001 for the remainder of the seven-mile length of the LHP. Since NCHRP-350 approval for the end anchor units had not been obtained, they were also shielded by existing sand barrel crash cushions. The initial Phase I test section was constructed in the center of the median, but the remaining seven-mile Phase II section was placed just outside the southbound shoulder, with asphalt paving for weed control.

This placement was chosen for two reasons. First, due to existing drainage drop inlets, some sections of the slopes in the center median were considered too steep for the WRSF to work safely, and there was no reasonable way to flatten them without extensive and expensive drainage modifications. Second, placement of the weed control pavement section under the barrier was desired to reduce the difficulty in mowing and upkeep of the median, and this strip most logically should be placed adjacent to the shoulder. This close placement would mean more nuisance hits than if it were placed in the center of the median.



3.0 COLLISION REPORTS AND FINDINGS

3.1 HISTORICAL COLLISION SUMMARIES

The Oklahoma Department of Public Safety supplied police reports to ODOT for research purposes. These reports included data pertaining to road conditions, collision analysis, and damage estimates. ODOT compiled data for the period prior to installing BRIFEN WRSF and for the period after installation. Much of the data following installation was obtained from the contractor doing the maintenance, since most of the hits did not result in a collision report being filed because the vehicles did not stop. This study provides a clear definition of the existing problems on LHP and how BRIFEN WRSF affected the situation.



3.2 IMPACTS

3.2.1 Analysis of Impacts Before Installation


For the one year prior to installation of BRIFEN WRSF, the LHP experienced six recorded serious median traffic collisions. All of these collisions were cross-over events, one involving a fatality, and one involving a rear-end collision. Given the width of the LHP median, it is likely that other vehicle incursions into the median occurred, but drivers were able to regain control or stop before crossing over into oncoming traffic, thus generating no collision report.

3.2.2 Analysis of Impacts After Installation

During the analysis period from August of 2001 through July of 2002, LHP experienced 126 impacts into the BRIFEN WRSF (see Table 3.1, APPENDIX A: COLLISION RECORDS), 43 of these being potential cross-over collisions. Each time, the BRIFEN WRSF performed as described by the manufacturer and prevented vehicles from crossing over into oncoming traffic.

No vehicles passed through the BRIFEN WRSF under any weather conditions, including wet pavement, snow and ice. The barrier was hit by drivers who were intoxicated, asleep at the wheel, experienced a tire blowout, or were forced off the road by other vehicles.

In addition, there were several instances where a vehicle impacted the BRIFEN WRSF in the same or nearby location of a previous hit. During the initial impacts posts were knocked down, but the system was still functional and able to resist additional collisions before crews could repair the damaged sections. In several collisions, the vehicles did not hit the BRIFEN WRSF in a normal "tracking" situation. This means the wheels did not hit the barrier in a stable, 25 degree- (or less) angle and at a speed of 100 kph (62.5 mph) or less. There were two separate collisions where a vehicle actually hit the BRIFEN WRSF head-on (90 degrees) at a speed greater than 50 mph and did not pass through the system. Several hits were estimated to have occurred at a 45 degree angle, even in a backward orientation. By still containing the impacting vehicles and preventing them from crossing the median, the BRIFEN WRSF proved to be performing well above the minimum requirements of NCHRP-350.





3.2.3 Fatalities and Injuries

Before the installation of BRIFEN WRSF, there had been 185 collisions on the LHP, resulting in six fatalities and 77 injuries between June 1, 1997, and May 31, 2000. Included in this number were four fatalities and six injuries resulting from cross-over collisions. ODOT considers a preventable fatality collision to be a \$2,800,000 cost impact to the economy. The existing average of more than one fatality per year was considered unacceptable.

Since the BRIFEN WRSF installation there has not been a single fatality or serious injury, although there have been numerous collisions recorded which had a high potential for resulting in a fatality had the BRIFEN WRSF not been in place.



Prior to installation, the LHP experienced a recorded average of ten collisions per year with an average of \$21,000 per collision in property damage. The completeness of the data is questionable because it is based only on crashes reported to the police. Some run-off-road events are assumed to have occurred, but are immeasurable. After installation, an average of 44 collisions per year was recorded with an average of \$5,000 each in property damage incurred.





DRY CONDITION
Frequency of BRIFEN hits
Day of the week

ALL CONDITIONS
Frequency of BRIFEN hits
Day of the week




WET CONDITION
Frequency of BRIFEN hits
Day of the week


4.0 MAINTENANCE AND REPAIR

4.1 WRSF MAINTENANCE AND REPAIR COSTS

Midstate Traffic Control Inc. of Oklahoma City provided all installation and maintenance for BRIFEN WRSF during this study. On average, considering repair costs of about \$63 per post replaced, a typical hit damaged an average of 4.71 posts, resulting in repair costs per incident of approximately \$297, including required traffic control. There were some additional costs added for emergency repairs. After one year, there were 128 impacts to the BRIFEN WRSF, 37 were northbound and 91 southbound. The southbound hits were more than two times as frequent as northbound due to the close proximity of the BRIFEN WRSF to the southbound traffic. As of December 31, 2002, the total impacts increased to 143. Southbound collisions were still double northbound.

ODOT and the Oklahoma City Police Department receive an average of about \$75 per post for insurance collection purposes. Some of the crashes result in no collision report or insurance claim since some vehicles flee the scene if not damaged or before officials arrive.





4.2 COST ANALYSIS

ODOT previously installed three miles of concrete median barrier along I-44 south of the LHP. This section attaches to the BRIFEN WRSF and is part of this experimental project. Installation and maintenance costs for both median barrier systems are shown in **Table 4.1**.

Table 4.1: Initial Cost Comparisons of Median Barrier Types

Median Barrier Type	Installation Cost (\$/mile)	Maintenance Costs (\$/mile/year)
WRSF	\$103,380	\$4,558*
Concrete	\$343,000	\$1,500**

*Current maintenance cost is \$52 per post, or \$3,759/mile/year at the same collision rate.

** One collision along this section required two sections of concrete wall to be replaced. Concrete wall estimated at \$250 per section, plus costs for traffic control.

4.3 CABLE BARRIER STUDIES FROM OTHER STATES

The repair costs from other states that have installed the three-wire rope system are shown in Table 4.2.

Table 4.2: Cost Comparisons with Other States Using Three-Wire Rope System

	Oklahoma BrifenWRSF	Oregon*	North Carolina
Study Year	2001	1998	1995
Miles of Barrier	7.0	14.5	13.7
Collisions/Year	42	20	N/A
Repairs/Year	24	40	71
Number of Injuries/Year	1	4	21
Number of Fatalities/Year	0	N/A	N/A
Prop. Damage/Year	\$260,000	N/A	N/A
Repair Cost/Post	\$63 **	\$206	\$65

* Data obtained from a 1998 study by the Oregon Department of Transportation on three-wire rope barrier systems.

** Current cost per post for repair is \$52/post (includes costs for traffic control).

4.4 REPAIRS

From the initial complete installation of the BRIFEN WRSF on the LHP, there was a total of 143 impacts. The cost to repair damages has been \$297 per collision, which includes traffic control and added costs for emergency repairs. Over the total length of seven miles the repair cost per year has been \$4,558 per mile.

5.0 CONCLUSIONS AND RECOMMENDATIONS

* BRIFEN WRSF has shown excellent performance during the 16-month installation period. There have been no cross-over crashes or fatalities and only one reported minor, personal injury. The BRIFEN WRSF has performed extremely well in actual field usage crashes, which in many cases are more severe and unpredictable than passing TL-3 tests conducted under ideal conditions.

* Maintenance of the BRIFEN WRSF has proven to be quick, easy and inexpensive, averaging \$297 per collision including traffic control. Typical five-post hits are repaired in less than 15 minutes by one person using only simple hand tools.

* Typical hits do not cause BRIFEN WRSF to fall to the ground, and it can generally sustain additional hits before being repaired. This is attributed to the patented weaving of the ropes between the posts and to the highly tensioned, pre-stretched ropes.

* Vehicle damage has typically been very light, and many vehicles continue on their way without stopping after a hit.

* Ease of post replacement makes the "socketed" post system the preferred alternative where high traffic volumes, curves, and other factors can be expected to cause numerous impacts. Driven posts would slightly reduce initial cost.

* Long distances of 3.2 km and 8.0 km (2.0 miles and 5.0 miles) between end anchors on the LHP system have proven to be satisfactory, and no loss of rope tension has been noted. Tension in the ropes has been checked frequently, and adjustment has not been necessary. Inspection of the wire ropes and rigging screws (turnbuckles) has shown no damage after sustaining 143 hits.

* BRIFEN WRSF has been well accepted by the local media, citizens of the area, and others for its visually pleasing appearance. It does not cause snow drifts or debris collection.

* Maximum deflection of BRIFEN WRSF on the LHP, noted from vehicle tracks, has been approximately 1.2 m (4'), while the NCHRP-350 TL-3 for WRSF is 2.4 m (7.8'). Both are less than the 3.4 to 3.7 m (11' to 12') typical of the standard three-cable system.

APPENDIX A: COLLISION RECORDS

Table 3.1

Incident #	Date	Day of the Week	# of Posts Damaged	Direction of Travel	Police Report	Road Condition	Repair Cost
1	08/11/01	SAT	11	SB	YES	Dry	\$715.00
2	08/11/01	SAT	3	NB	YES	Dry	\$195.00
3	08/12/01	SUN	3	NB	NO	Dry	\$195.00
4	08/17/01	FRI	10	SB	YES	Dry	\$650.00
5	08/17/01	FRI	3	SB	YES	Dry	\$195.00
6	08/18/01	SAT	10	NB	YES	Dry	\$650.00
7	08/30/01	THR	32	SB	YES	Dry	\$2,080.00
8	08/31/01	FRI	16	SB	YES	Dry	\$1,040.00
9	09/14/01	FRI	10	NB	YES	Dry	\$650.00
10	09/15/01	SAT	2	NB	NO	Dry	\$130.00
11	09/15/01	SAT	7	NB	YES	Dry	\$455.00
12	09/22/01	SAT	4	NB	NO	Dry	\$260.00
13	10/01/01	MON	2	NB	YES	Dry	\$130.00
14	10/08/01	MON	7	SB	YES	Dry	\$455.00
15	10/08/01	MON	4	SB	NO	Dry	\$260.00
16	10/08/01	MON	7	NB	NO	Dry	\$455.00
17	10/10/01	WED	5	SB	YES	Dry	\$325.00
18	10/25/01	THR	4	SB	YES	Dry	\$260.00
19	10/26/01	FRI	3	SB	YES	Dry	\$195.00
20	10/27/01	SAT	10	SB	NO	Dry	\$650.00
21	11/05/01	MON	6	NB	YES	Dry	\$390.00
22	11/19/01	MON	5	SB	NO	Dry	\$325.00
23	11/26/01	MON	3	NB	NO	Dry	\$195.00
24	11/26/01	MON	5	SB	NO	Dry	\$325.00
25	11/28/01	WED	19	SB	YES	Ice & Snow	\$1,235.00
26	11/28/01	WED	1	SB	YES	Ice & Snow	\$65.00
27	11/28/01	WED	2	SB	NO	Ice & Snow	\$130.00
28	11/28/01	WED	2	SB	NO	Ice & Snow	\$130.00
29	11/28/01	WED	1	NB	NO	Ice & Snow	\$65.00
30	11/28/01	WED	2	SB	NO	Ice & Snow	\$130.00
31	11/28/01	WED	1	SB	NO	Ice & Snow	\$65.00
32	11/28/01	WED	1	SB	NO	Ice & Snow	\$65.00
33	11/29/01	THR	3	SB	NO	Ice & Snow	\$195.00
34	11/29/01	THR	1	SB	NO	Ice & Snow	\$65.00
35	11/29/01	THR	1	SB	NO	Ice & Snow	\$65.00
36	12/08/01	SAT	3	SB	NO	Dry	\$195.00
37	12/10/01	MON	3	SB	NO	Dry	\$195.00
38	12/25/01	TUE	5	SB	YES	Dry	\$325.00
39	12/30/01	SUN	1	SB	NO	Ice & Snow	\$65.00
40	12/30/01	SUN	1	SB	NO	Ice & Snow	\$65.00
41	12/30/01	SUN	2	SB	NO	Ice & Snow	\$130.00
42	12/30/01	SUN	1	SB	NO	Ice & Snow	\$65.00
43	12/30/01	SUN	1	SB	NO	Ice & Snow	\$65.00
44	12/30/01	SUN	1	NB	NO	Ice & Snow	\$65.00
45	12/30/01	SUN	2	NB	NO	Ice & Snow	\$130.00
46	12/30/01	SUN	4	NB	NO	Ice & Snow	\$260.00
47	12/30/01	SUN	3	SB	NO	Ice & Snow	\$195.00
48	12/30/01	SUN	1	NB	NO	Ice & Snow	\$65.00
49	12/30/01	SUN	2	SB	NO	Ice & Snow	\$130.00
50	12/30/01	SUN	2	SB	NO	Ice & Snow	\$130.00
51	12/31/01	MON	2	SB	YES	Ice & Snow	\$130.00
52	12/31/01	MON	4	NB	NO	Ice & Snow	\$260.00
53	01/01/02	TUE	3	NB	NO	Dry	\$195.00
54	01/22/02	TUE	4	SB	NO	Dry	\$260.00
55	01/28/02	MON	4	SB	NO	Dry	\$260.00
56	01/30/02	WED	2	SB	YES	Dry	\$130.00
57	01/30/02	WED	6	NB	NO	Dry	\$390.00
58	02/11/02	MON	4	SB	YES	Dry	\$260.00

Incident #	Date	Day of the Week	# of Posts Damaged	Direction of Travel	Police Report	Road Condition	Repair Cost
59	02/11/02	MON	2	NB	YES	Dry	\$130.00
60	02/11/02	MON	6	NB	YES	Dry	\$390.00
61	02/25/02	MON	5	SB	YES	Dry	\$325.00
62	03/01/02	FRI	4	NB	NO	Ice & Snow	\$260.00
63	03/01/02	FRI	6	SB	NO	Ice & Snow	\$390.00
64	03/01/02	FRI	3	SB	NO	Ice & Snow	\$195.00
65	03/01/02	FRI	1	SB	NO	Ice & Snow	\$65.00
66	03/01/02	FRI	1	SB	NO	Ice & Snow	\$65.00
67	03/01/02	FRI	4	SB	NO	Ice & Snow	\$260.00
68	03/01/02	FRI	2	SB	NO	Ice & Snow	\$130.00
69	03/01/02	FRI	3	SB	NO	Ice & Snow	\$195.00
70	03/02/02	SAT	3	SB	NO	Ice & Snow	\$195.00
71	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
72	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
73	03/02/02	SAT	2	NB	NO	Ice & Snow	\$130.00
74	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
75	03/02/02	SAT	4	SB	NO	Ice & Snow	\$260.00
76	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
77	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
78	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
79	03/02/02	SAT	3	SB	NO	Ice & Snow	\$195.00
80	03/02/02	SAT	4	SB	NO	Ice & Snow	\$260.00
81	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
82	03/02/02	SAT	3	SB	NO	Ice & Snow	\$195.00
83	03/02/02	SAT	1	NB	NO	Ice & Snow	\$65.00
84	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
85	03/02/02	SAT	3	SB	NO	Ice & Snow	\$195.00
86	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
87	03/02/02	SAT	4	SB	NO	Ice & Snow	\$260.00
88	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
89	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
90	03/02/02	SAT	5	SB	NO	Ice & Snow	\$325.00
91	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
92	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
93	03/02/02	SAT	2	SB	NO	Ice & Snow	\$130.00
94	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
95	03/02/02	SAT	1	SB	NO	Ice & Snow	\$65.00
96	03/15/02	FRI	5	SB	NO	Dry	\$325.00
97	03/15/02	FRI	6	SB	NO	Dry	\$390.00
98	03/25/02	MON	4	SB	NO	Dry	\$260.00
99	04/02/02	TUE	9	SB	YES	Dry	\$585.00
100	04/03/02	WED	2	NB	NO	Dry	\$130.00
101	04/05/02	FRI	8	SB	YES	Dry	\$520.00
102	04/08/02	MON	6	NB	NO	Dry	\$390.00
103	04/08/02	MON	1	NB	NO	Dry	\$65.00
104	04/17/02	WED	11	SB	NO	Dry	\$715.00
105	04/22/02	MON	4	NB	NO	Dry	\$260.00
106	04/22/02	MON	7	SB	NO	Dry	\$455.00
107	05/09/02	THR	13	NB	NO	Dry	\$845.00
108	05/10/02	FRI	1	NB	NO	Dry	\$65.00
109	05/11/02	SAT	7	NB	NO	Dry	\$455.00
110	05/12/02	SUN	3	SB	NO	Dry	\$195.00
111	05/14/02	TUE	7	NB	NO	Dry	\$455.00
112	05/17/02	FRI	4	SB	NO	Dry	\$260.00
113	05/21/02	TUE	10	SB	YES	Dry	\$650.00
114	05/24/02	FRI	4	SB	YES	Dry	\$260.00
115	05/24/02	FRI	7	NB	NO	Dry	\$455.00
116	06/04/02	TUE	6	SB	YES	Dry	\$390.00
117	06/21/02	FRI	4	NB	NO	Dry	\$260.00
118	06/22/02	SAT	4	SB	NO	Dry	\$260.00
119	06/20/02	THR	4	NB	NO	Dry	\$260.00

Incident #	Date	Day of the Week	# of Posts Damaged	Direction of Travel	Police Report	Road Condition	Repair Cost
120	07/02/02	TUE	11	NB	NO	Dry	\$715.00
121	07/02/02	TUE	2	SB	NO	Dry	\$130.00
122	07/15/02	MON	3	NB	NO	Dry	\$195.00
123	07/17/02	WED	4	NB	NO	Dry	\$260.00
124	07/17/02	WED	1	SB	NO	Dry	\$65.00
125	07/25/02	THR	23	SB	NO	Dry	\$1,495.00
126	07/31/02	WED	18	SB	NO	Dry	\$1,170.00
TOTALS			557				\$36,205.00

Totals thru 07/31/02

126 hits, 1 minor injury, no fatalities or cross-over crashes

Appendix 8



OKLAHOMA DEPARTMENT OF TRANSPORTATION

June 24, 2004

Oklahoma DOT Experience with Brifen Wire Rope Safety Fence on Lake Hefner Parkway in Oklahoma City

Almost 3 years have passed since the Brifen Wire Rope Safety Fence (WRSF) was installed on Lake Hefner Parkway in Oklahoma City, and it is appropriate to look at how it has performed. This 7-mile project was the first Brifen WRSF installed anywhere in the United States and we frequently are asked by other states and local entities what we think of its performance. Since I am involved in maintaining safety appurtenances in this metropolitan area, I have closely watched the Brifen WRSF on Lake Hefner Parkway. Some comments are:

- This 7-mile system was installed in two sections. One section is 2 miles long and the other is 5 miles in length. There is an anchor at the end of each section (4 total). There are no intermediate end anchors, which makes for a simple, straightforward installation and reduced future maintenance.
- As of May 10, 2004 the system had 238 hits, requiring replacement of 1279 posts for an average of 5.3 posts per hit. Maintenance (by contract) costs \$51.00 per post replaced, for an average repair cost per hit of \$270.00. This covers material, labor and traffic control. Repair of a similar length of w-beam guardrail would be far more expensive and time consuming. (3 sections of 25' rails, post, bolts, etc. plus heavy equipment)
- To our knowledge, police accident reports have only been filed on approximately 30% of the hits, meaning 70% of the vehicles received only minor damage and drivers were uninjured and able to drive away. Only 3 injuries have been reported as far as we know. A number of the hits have been at very high speed and at impact angles approaching 90°. The largest vehicle to impact the system was a full size school bus. The bus was re-directed safely after the driver had a heart attack. This is a remarkable record compared to any other type of barrier (w-beam, concrete, etc), which generally cause extensive vehicle damage when hit and injuries can be severe.
- One of the major benefits of the Brifen WRSF has been the short time required to make repairs. A typical 5-post repair is usually made in about 15 minutes by one person using only hand tools. Two people can do it even faster. This means crews are not in harms way for very long and there is little or no delay to traffic.
- The WRSF normally stays up after a hit, and has successfully re-directed additional nearby hits prior to being repaired. It does not fall to the ground after a hit like the 3-cable systems are known to do, which would leave a gap in the protection. We have had only a few cases, when many posts were knocked out, that the cables have dropped down to the ground. In those cases repairs were made within 2 hours as required by the contract for those type hits.
- In an effort to reduce costs for vegetation control, an asphalt "mowing strip" was placed under the WRSF for the full length of the project. It is 4 feet wide and 4" thick and placed adjacent to the southbound lanes. The WRSF is centered in this strip. This adds cost and is not very effective since grass has now over grown much of the strip and hand mowing is still needed. Use of a soil sterilant herbicide may be more cost-effective.

In summary, our experience with Brifen WRSF has been excellent. We have had no fatalities and only 3 barrier-involved injuries to date as far as we know. It is a highly cost effective barrier that has served the traveling public extremely well. In fact, the Lake Hefner Parkway Brifen WRSF won a prestigious Federal Highway Administration National Safety Award in November 2003 in competition with many safety projects from all around the country.

We hope to continue its use on other sites as funding becomes available. We do not support using other unproven cable barrier systems when we already have a system that we know saves lives and property damage, and is easy and inexpensive to repair. A side benefit is that Brifen WRSF is manufactured right here in Oklahoma City, providing needed jobs for local workers.

Randy B. Lee, P.E.
Division IV Traffic Engineer

"The mission of the Oklahoma Department of Transportation is to provide a safe, economical, and effective transportation network for the people, commerce and communities of Oklahoma."

AN EQUAL OPPORTUNITY EMPLOYER

Appendix 9

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Scoping

When is placement of a median barrier considered?

New Construction? **Yes**

Reconstruction? **Yes**

Resurfacing/Restoration/Rehabilitation (3R)?

Response to crash history? (Project initiated to address safety concern) **Yes**

Systemwide policy to implement barrier?

Political?

Other?

Warrants

How does the agency decide when a median barrier is warranted?

Cross section, traffic, alignment, etc?

Crash history? **Yes**

Across the board policy?

Case-by-case? **Yes**

How does the agency decide when a high tension cable median barrier should be used, rather than some other system [e.g., cost, deflection, median width, maintenance, design vehicle, terrain, aesthetics, snow plowing, soil conditions, other]?

- **Cost**
- **Deflection**
- **Median Width**
- **Maintenance**
- **Aesthetics**

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Design

What is the status of high tension cable barrier in your Agency? **We are evaluating the different kinds.**

What high tension cable median barrier systems do you allow? **Brifen, Safence, Cass (under evaluation)**

What are the differences that affect your choice of systems?

What is the maximum typical slope on which you place the barrier? **6:1**

What guidelines do you use for coordination of the barrier and median slopes?

What location(s) do you use for placement of the barrier, along shoulder, near center of median, intermediate? Describe. **We have placed it along the shoulder, near center and are evaluating it.**

Do you place a mow strip under the barrier?

Under what conditions?

What material? Width? Thickness?

We placed mow strip under the Barrier for two (2) projects and did not for two (2) and are evaluating it.

Have you made any special designs due to frost heave concerns? **No**

Have you made any special designs due to soil conditions? **No**

How do you accommodate median crossovers? Are you eliminating crossovers? **No**

How do you accommodate mainline bridges? **We go along on side of bridge.**

How do you coordinate with other safety barriers and/or impact attenuators? **With concrete barriers we place it behind it, place it between impact attenuators.**

How do you coordinate with existing fixed objects, such as bridge piers, inlets, sign bridges? **We go along one side of it and keep the protection for the fixed objects.**

What other safety treatments do you apply in conjunction with the barrier?

Shoulder rumble strips? **No**

Delineators? **Yes**

Other?

Have you used socketed posts? **Yes**

Have you used driven posts/sockets? **No**

Do you place the high tension cable median barrier only in freeway medians? **Yes**

What other locations? **None**

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

What is the longest run of cable between anchors? **5 miles**

Design requirements for curves and tapers, e.g. post spacing, minimum and maximum criteria?

How are posts in rock detailed? **Not encountered**

Design (continued)

Is estimated deflection for a given post spacing based on the manufacturer's recommended design? If not, explain. **Yes**

Do you consider 3-cable and 4-cable systems to be equivalent? **We are experimenting with both 3-cable and 4-cable systems.**

Have you or do you plan to use TL4 cable guard? What criteria do you use? **?**

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Installation

What production rate is typical [for both L.F. of cable guard and terminal installation]?
[Does it vary by location (mid-median vs. edge of shoulder)? Does it vary by product?]

Were there any problems with construction of the mow strip (if used)?

Describe any difficulties with installation of the cable barrier.

Have you experienced any problems with installations in rock?

How much time is required between concrete post installation and tensioning?

Have you experienced any quality problems with manufactured materials?

Have you experienced any quality problems with constructed materials, e.g. concrete?

Do you use each manufacturer's recommended tension meter for installation? Do you have a preference?

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Performance

Has the system allowed any "design" vehicles to penetrate?

If so, why?

Has the system caused any rollovers or other severe consequences?

What factors contributed? **No**

Has the system remained serviceable between the time of an initial impact and start of repairs? **Yes**

Has the system contained any vehicles beyond the "design" limitations (speed or mass)?

Has observed deflection matched design deflection? **Yes**

Have you observed any cracking, spalling, break-offs, etc in the concrete posts as a result of impact? Weather? **No**

Have wet medians, poor soils, and/or frost resulted in barrier shifting or jacking up? If so, has this affected performance? **No**

Is the system cost effective (in terms of reducing crash/improving safety vs the amount of money spent)? **Yes**

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Maintenance

Have the system anchors remained stable? **Yes**

Who does the repairs? (State forces, or contract forces) **Both for Brifen (Contractor) & Safence (State forces)**

How is training handled? **Contractor (supplier trains – part of contract). Require Contractor to have certified training.**

How difficult have repairs been? **Simple**

Have repair parts been readily available? How much time is required for delivery? **Yes. For Brifen - insignificant.**

Have repairs caused any confusion regarding parts or methods? **No**

Have winter repairs caused any special problems (posts frozen in sockets, etc.) **No**

Has tension been checked after repairs? **Yes, at first periodically. It has been ok to check less now.**

Does the cable hold correct tension after an impact? **Yes**

Does the system cause complications for mowing? For snow plowing? **Yes. For snow plowing no problem.**

Does the system cause complications for other maintenance activities? **No**

Does the system cause complications for emergency responders and police? Were special training or informational sessions offered? **We were concerned but we have not had any problems.**

How much time is spent on-site for the average repair? Is more time needed in the winter? **Avg. 20 Minutes, same for winter.**

Have any repairs required cable replacement? **No** Have any repairs required replacement of concrete posts or anchors? **No**

What parts are required for the typical repair? **Just the posts and some of the caps**

Do you keep an inventory of parts on hand? **No – contractor does.**

Do you keep cable on hand? How do you estimate the inventory of parts to keep on hand? Where are they stored? What parts are stored inside? What parts are stored outside? **It is not an issue for us.**

Does maintenance prefer a mid-median or shoulder location? **Mid Median, we prefer it to be off set from the center of the median.**

QUESTIONS FOR ASAP TOUR FOR MEDIAN CROSSOVER CRASH COUNTERMEASURES

Maintenance (continued)

Has maintenance observed any frost heave? If so, how have they handled it? **No**

Has maintenance observed any salt damage? **No**

Does cable hold tension over time? **Yes**

How many tension meters and other specialized tools does each maintenance unit have? **None, contractor has one.**

How do maintenance workers feel about having to maintain the system with greater exposure to Interstate traffic? **Contractor does it for Brifen.**

How does law enforcement feel about not being able to go through the ditches to catch speeders going in the other direction? **We have not had any complaints.**

Appendix 10

SPECIAL SPECIFICATION

5084

Cable Barrier System

1. **Description.** Furnish and install a cable barrier system and cable barrier terminal sections at the locations shown on the plans.
2. **Materials.** Furnish a new cable barrier system and cable barrier terminal sections in accordance with the details shown on the plans and on the manufacturer's shop drawings, or equal as approved.

Furnish Class C concrete in accordance with Item 421, "Hydraulic Cement Concrete."

Furnish delineators as shown on the plans and in accordance with Item 658, "Delineator and Object Marker Assemblies."

3. **Construction.** Install cable barrier system and cable barrier terminal sections in accordance with the details shown on the plans and manufacturer recommendations. Place posts into steel sleeves in a concrete foundation, unless otherwise shown on the plans. Locate terminal sections at locations as shown on the plans. Repair or replace damaged parts immediately. Provide the Engineer with an installation and repair manual specific to the cable barrier system and cable barrier terminal sections.
4. **Measurement.** This Item will be measured by the foot of cable barrier system and by the each cable barrier terminal section installed.
5. **Payment.** The work performed and the materials furnished in accordance with this Item and measured as provided under "Measurement" will be paid for at the unit price bid for "Cable Barrier System" and "Cable Barrier Terminal Section." This price is full compensation for furnishing cable barrier system, cable barrier terminal section, concrete, delineators, equipment, labor, tools, and incidentals.

Shielding of end anchor sections if needed will be paid for under other Items.

Delineators will not be measured or paid for directly, but will be considered subsidiary to this Item.

Appendix 11

Selected Photographic Material – Texas



1. CASS Post on I-20



2. CASS Installation on I-20



3. Detail CASS post



4. CASS Turnbuckle



5. TTI's end treatment post on CASS



6. TTI's anchor post – Top view



7. TTI's anchors



8. Inappropriate turnbuckle placement



9. Trailer for carrying repair parts



10. Trailer compartments




11. Brifen installation on I-20




12. Brifen anchor system


Appendix 12



TYPICAL SECTION




Detail A




Jimmy F. Bodiford, P.E.
3-23-05

FED. RD. DIST. NO.	FEDERAL AID PROJECT NO.	SHEET NO.
6		2
STATE	COUNTY	
TEXAS	PARKER	
CONTRACT NO.	SECTION	HIGHWAY NO.
0314	07	032 IH 20




RUN NO.	FROM	TO	EXCAVATION (CY)	SEEDING (SY)	VEG WATER (MG)	ACP (TY B)	WIRE ROPE/CABLE (LF)	TERMINAL SECT (EA)
1	BEGIN PROJECT	PATRICK CREEK	109	1301	27.4	215	2827	2
2	PATRICK CREEK	SIGN BRIDGE	64	765	16.1	127	1620	2
3	SIGN BRIDGE	SP 312	119	1420	29.9	235	3093	2
4	SP 312	DENNIS RD	66	791	16.7	131	1679	2
5	DENNIS RD	SANCHEZ CREEK	278	3328	70.0	550	7388	2
6	SANCHEZ CREEK	OLD BROCK RD	99	1184	24.9	196	2562	2
7	OLD BROCK RD	OLD DENNIS RD	228	2735	57.5	452	6053	2
8	OLD DENNIS RD	FM 1884	173	2073	43.6	342	4563	2
SHEET TOTALS			1136	13597	286.1	2248	29785	16

PROJECT LAYOUT




Jimmy F. Bodiford, P.E.
3-23-05

FED. RD. DIST. NO.	6	FEDERAL AID PROJECT NO.		SHEET NO.	19
STATE	TEXAS	COUNTY	PARKER		
CONTRACT	0314	SECTION	07	JOB	032
				HIGHWAY NO.	1H 20




TYPICAL PLACEMENT AT BRIDGE END DETAIL




TYPICAL REMOVAL DETAIL

LOCATION	REMOVE TAS (EA)	REMOVE MBGF (LF)	REMOVE GET (EA)
SIGN BRIDGE	2	250	2
SP 312	2	350	2
DENNIS RD	2	250	2
OLD BROCK RD	2	250	2
OLD DENNIS RD	2	250	2
PROJECT TOTALS	10	1350	10



TYPICAL PLACEMENT AT BRIDGE COLUMNS - DETAIL 1



TYPICAL PLACEMENT AT BRIDGE COLUMNS - DETAIL 2



Jimmy F. Boudford, P.E.
3-23-05

© 2005 by Texas Department of Transportation
All Rights Reserved

FED. RD. DIST. NO.	6	FEDERAL AID PROJECT NO.		SHEET NO.	20
STATE	TEXAS	COUNTY	PARKER		
CONTRACT	0314	SECTION	07	JOB	032
				HIGHWAY NO.	1H 20









ROADWAY
DETAILS

DISCLAIMER:
The use of this standard is governed by the "Texas Engineering Practice Act". No warranty of any kind is made by TxDOT for any purpose whatsoever. TxDOT assumes no responsibility for the conversion of this standard to other formats or for incorrect results or damages resulting from its use.

The diagram illustrates two methods of joining rope sections:

- Top Diagram (Correct Method):** Shows two rope sections joined using a **Threoded Terminal** at each end. The terminals are connected by a **HDPE Washer** and a **Steel Washer (if required)**, secured with a **Mechanical Fitting**. The length of the rope sections is labeled **Tail rope to required length**.
- Bottom Diagram (Incorrect Method):** Shows two rope sections joined by simply twisting them together, labeled **Tail rope to required length** and **Tensile Fitting**.

ROPE COMPONENTS AND TENSION CHART



WIRE ROPE SAFETY FENCE
(Briften USA, Safety Fence)


FED. RD. DIST. NO.	FEDERAL AID PROJECT NO.	SHEET NO.
6		21
STATE	STATE DIST. NO.	COUNTY
TEXAS	FTW	PARKER
CONT.	SECT.	JOB HIGHWAY NO.
0314	07	032 1H 20

DISCLAIMER:
The use of this standard is governed by the "Texas Engineering Practice Act". No warranty of any kind is made by TxDOT for any purpose whatsoever. TxDOT assumes no responsibility for the conversion of this standard to other formats or for incorrect results or damages resulting from its use.





GENERAL NOTES

1. For additional information, contact Trinity Industries, Inc. at 1-800-527-6050.
2. All concrete shall be class C.
3. For cable barrier installation lengths and terminal cable (CCT requirements. (See the manufacturer's product manual)
4. For payment see special specification "Cable Barrier System".
5. The CASS system is designed for bi-directional traffic flows. See the manufacturer's product manual for placement adjacent to guardrail end treatments.
6. CASS shall be installed on median shoulders or in depressed medians with slopes of 6:1 or flatter without obstructions, depressions, etc. that may significantly affect the stability of an errant vehicle.
7. CASS may be installed on either side of the median. CASS post may be socketed or driven design and shall be alternately rotated 180 degrees so that every other post is facing traffic flow.
8. Rebar ring is not required if installed in a 3 ft. (min.) width now strip of 8 in. (min.) asphalt depth or 4 in. (min.) reinforced concrete depth. If minimum requirements are not met contact Trinity Industries to discuss footings.
9. See the Texas MUTCD for proper delineation.



SECTION A-A
(TYPE D POST)




BASE-PLATED POST
(TYPE B POST)


**FOR USE ON CONCRETE:
BASE-PLATED POST DESIGN IS NOT
TO BE USED WITH CCT POSTS**

Anchor Options



1. $\frac{5}{8}$ " x 8" all threaded Rod (A449) with epoxy.
 2. $\frac{5}{8}$ " Mechanical anchor.
- (Min. embedment in concrete = 6".
Min. pullout strength = 10,000 lbs.)





(CABLE RELEASE POST)



DETAIL B



DETAIL A







CABLE SAFETY SYSTEM
(Trinity Industries Inc.)

(Trinity Industries Inc.)

FILE#	DN	CA	DM	CA
REVISIONS	DISTINCT	FEDERAL AID PROJECT		SHEET
Δ REVISED 6.28.05	FTW			22
	COUNTY	CONTROL	SECT	JOB
	PARKER	03407	032	111D

LEVELS	L	20
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		


DISCLAIMER:
The use of this standard is governed by the "Texas Engineering Practice Act". No warranty of any kind is made by TxDOT for any purpose whatsoever. TxDOT assumes no responsibility for the conversion of this standard to other formats or for incorrect results or damages resulting from its use.



GENERAL NOTES

- For additional information, contact Gibraltar, Inc. at 1-800-495-8957.
- All concrete shall be class C.
- For additional information: See the manufacturer's product manual.
- For payment see special specification "Cable Barrier System".
- The GCBS system is designed for bi-directional traffic flows. See the manufacturer's product manual for placement adjacent to quodrail end treatments.
- GCBS shall be installed on median shoulders or in depressed medians with slopes of 6:1 or flatter without obstructions, depressions, etc. that may significantly affect the stability of an errant vehicle.
- GCBS may be installed on either side of the median. Post may be socketed or driven design.
- See the Texas MUTCD for proper delineation.

CABLE TENSION CHART	
F	lbF
-10	8210
0	7819
10	7447
20	7069
30	6677
40	6301
50	5928
60	5536
70	5155
80	4773
90	4390
100	4009
110	3627




SOCKETED POST OPTION

(TYPE S POST)
* If a Mow Strip is used the socket depth may be decreased to 2'-6".

DRIVEN POST OPTION

(TYPE D POST)



GIBALTAR CABLE
BARRIER SYSTEM
(Gibraltar Inc.)

ADDED 6.28.05

FILE#	DN#	CK#	DN#	CK#
REVISIONS				
	FTW			
	COANT			
	PARKEA			
	03407032			
	1410			

Appendix 13

MAINTENANCE / REPAIR LOG
Wire Cable Median Barrier Systems

ACCIDENT #6 INFORMATION			
DATE:	<u>7/12/2005</u>	LIGHT CONDITION:	NIGHT
TIME:	<u>UNKNOWN</u>	ROAD CONDITION:	DRY
HIGHWAY:	<u>IH 20</u>	APPROX. REFERENCE MARKER:	<u>MM 419</u>
DIRECTION OF TRAVEL:	<input checked="" type="checkbox"/> EAST	<input type="checkbox"/> WEST	
VEHICLE TYPE:	<input checked="" type="checkbox"/> CAR	<input type="checkbox"/> TRUCK	<input type="checkbox"/> SEMI <input type="checkbox"/> UNKNOWN
PROPERTY DAMAGE ONLY:	<input type="checkbox"/> YES	<input type="checkbox"/> NO	NUMBER OF INJURIES: <u>N/A</u>
(No Injuries/Fatalities)			NUMBER OF FATALITIES: <u>N/A</u>
PREVENT CROSSOVER:	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	
BRIEF DESCRIPTION OF INCIDENT:			
DPS CALLED IN DAMAGED TO WIRE ROPE BARRIER. VEHICILE WAS EVADING ARREST.			
REFER TO # 7, 9 & 10 PIC'S			

REPAIR INFORMATION			
DATE:	<u>7/12/2005</u>		
TIME:	<u>8:30 AM</u>		
PRODUCT:	<input checked="" type="checkbox"/> BRIFEN	<input type="checkbox"/> TRINITY	# OF EMPLOYEES: <u>2</u>
			# OF HOURS: <u>6</u>
# OF POSTS REPLACED:	<u>27</u>		MATERIAL COST: <u> </u>
			LABOR COST: <u> </u>
ENDTREATMENT INVOLVED:	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	